

High Speed Tool Steel
On Lathe Work

C. E. Hayes
F. N. Wilson

1906

621.94
H 32

ARMOUR
INST. OF TECH. LIB.
CHICAGO.



Illinois Institute
of Technology
UNIVERSITY LIBRARIES

AT 36
Hayes, Charles Edward
High Speed Tool Steel On
Lathe Work

For Use in Library Only

HIGH SPEED TOOL STEEL

932
87
a

ON

LATHE WORK

A THESIS

PRESENTED BY

CHARLES EDWARD HAYES

FRED NORWOOD WILSON

TO THE

PRESIDENT AND FACULTY

OF

ARMOUR INSTITUTE OF TECHNOLOGY

FOR THE DEGREE OF

BACHELOR OF SCIENCE IN MECHANICAL ENGINEERING

HAVING COMPLETED THE PRESCRIBED COURSE OF STUDY IN

MECHANICAL ENGINEERING

JUNE 4 1906 9

ILLINOIS INSTITUTE OF TECHNOLOGY
PAUL V. GALVIN LIBRARY
35 WEST 33RD STREET
CHICAGO, IL 60616

Approved
J. F. Schmitt
H. M. Raymond Dean of Eng. Studies

HIGH SPEED TOOL STEEL

IN A THE WORK

A THESIS

CHARLES EDWARD HAYES

FRANK MURDOCK WILSON

RESIDENT AND FACULTY

ARMOUR INSTITUTE OF TECHNOLOGY

BACHELOR OF SCIENCE IN MECHANICAL ENGINEERING

HAYES COMPLETED THE RESEARCH WORK IN 1908

MECHANICAL ENGINEERING

JUNE 4 1908

ARMOUR INSTITUTE OF TECHNOLOGY

PAUL M. CHAMBERLAIN LIBRARY

36 WEST 32ND STREET

CHICAGO, ILL.

HIGH SPEED TOOL STEEL ON LATHE WORK.

The object of this thesis has been to work along the following lines.

First: To run brake tests on the lathe with a view to determining the efficiency of the lathe under a variety of loads, and speeds. To calibrate the lathe so that any desired number of revolutions per minute of the spindle may be secured by referring to the tables accompanying this thesis.

Second: To conduct a series of tests of high speed tool steel on cast iron, using six different standard grades of steel, determining the capacity of each grade of steel, the maximum amount of stock that can be removed in a given time using certain depths of cut and cutting speeds, without breaking down the tool.

Third: To fit up a drill press for the purpose of making comparative hardness tests on the cast iron specimens used in the tests.

PRELIMINARY DISCUSSION

Cast iron is extensively used in engineering work because of its low first cost, its strength, and the facility with which it can be cast into any desired form. The great variety of machine parts made from cast iron, and brought to the desired shape in lathes, by means of some form of tool steel, tends to make the subject of this thesis of interest to the commercial world.

During the last five years a new material known as "high speed tool steel" has been revolutionizing modern machine shop practice. This steel may be used for any shape or form of tool, and gives a very large material increase of output and saving of time in machin-

The object of this thesis has been to work along the following

lines.

First: To run brake tests on the lathe with a view to determining the efficiency of the lathe under a variety of loads, and speeds. To calibrate the lathe so that any desired number of revolutions per minute of the spindle may be secured by referring to the tables accompanying this thesis.

Second: To conduct a series of tests of high speed tool steel on cast iron, using six different standard grades of steel, determining the capacity of each grade of steel, the maximum amount of stock that can be removed in a given time using certain depths of cut and cutting speeds, without breaking down the tool.

Third: To fit up a drill press for the purpose of making comparative hardness tests on the cast iron specimens used in the tests.

PRELIMINARY DISCUSSION

Cast iron is extensively used in engineering work because of its low first cost, its strength, and the facility with which it can be cast into any desired form. The great variety of machine parts made from cast iron, and brought to the desired shape in lathes, by means of some form of tool steel, tends to make the subject of this thesis of interest to the commercial world.

During the last five years a new material known as "high speed tool steel" has been revolutionizing modern machine shop practice. This steel may be used for any shape or form of tool, and gives a very large material increase of output and saving of time in machine-

ing ,with a durability of from five to thirty times that of the best crucible cast steels. By means of this "high speed steel", steel bars can be machined and turned at a maximum speed of 500 feet per minute, and cast iron drilled at the rate of 25 inches per minute. The cutting speeds of the ordinary carbon crucible steels are usually from 30 to 50 feet per minute.

In the manufacture of "high speed steel" it is necessary to use the purest quality of iron and alloys. The steel is made by various steel companies, each company having its own method and composition for making its special grade. The combinations usually used are iron and carbon with (1) tungsten and chromium, (2) molybdenum and chromium, (3) tungsten, molybdenum, and chromium. Each one of these metals has its influence on the quality of the steel.

The main requirements of a good "high speed steel" demand that it should withstand the very high temperature due to friction when cutting at a high speed. In our own tests we have noted on several occasions that certain of the steels used were able to cut off stock without failing when the nose of the tool was at a red heat. "High speed tools" are hardened in air, in a cold air blast, or in oil. The "high speed steel" can be used for lathe tools, planer tools, taps, milling cutters, reamers, formed cutters, twist drills, undercut tools, boiler punches, drawing dies, pneumatic chisels, and pneumatic riveters.

When annealed the steel is soft and can be forged, ^{and machined} as easily as ordinary carbon steel. The unannealed steel is glass hard.

ing, with a durability of from five to thirty years, that of the best available steel. By means of this "high speed steel", steel bars can be machined and turned at a maximum speed of 500 feet per minute, and cast iron drilled at the rate of 25 inches per minute. The cutting speeds of the ordinary carbon steels are usually from 25 to 40 feet per minute.


In the manufacture of "high speed steel" it is necessary to use the purest quality of iron and alloys. The steel is made by various steel companies, each company having its own method and composition for making its special grade. The compositions usually used are iron and carbon with (1) tungsten and chromium, (2) molybdenum and chromium, (3) tungsten, molybdenum, and chromium, each one of these metals has its influence on the quality of the steel.

The main requirements of a good "high speed steel" are that it should withstand the very high temperatures due to friction when cutting at a high speed. In our own tests we have noted on several occasions that certain of the steels used were able to cut off stock without failing when the nose of the tool was at a red heat. "High speed steels" are hardened in air, in a cold air blast, or in oil. The "high speed steel" can be used for lathe tools, planer tools, milling cutters, twist drills, and reamers.


When annealed the steel is soft and can be worked easily as ordinary carbon steel. The unannealed steel is glass hard.

DESCRIPTION OF THE LATHE

The tests were all made on a Lodge and Shipley 16" patent head high speed lathe, of the latest pattern. The lathe is directly connected to a Northern variable speed motor of 2 1/2 rated electrical horse power. This motor takes its power from leads connected to the 110 volt circuit. At rated load the the motor takes 20 amperes, and is guaranteed to run 100% overload for short periods without sparking or overheating. The lathe used is of somewhat



lighter construction than the one shown in the figure, otherwise it is of the same design. The lathe will swing a diameter of nine inches over the carriage. The motor, and the resistance and control




Headstock and Back Gears.

er boxes, are mounted on an extended cabinet leg at the end of the lathe. The motor shaft is connected to the lathe spindle through a friction clutch and gear-

The force were all made on a single and the same
near high speed level of the motor. The same is fixed
is connected to a Western variable speed motor of 3 1/2 hp rated
electrical power. The motor takes its power from a 110 volt
connected to the 110 volt circuit. It takes from the motor takes
20 amperes, and is guaranteed to run and overload for short periods
without working at overloading. The same need be 25 amperes

lighter construction than the one shown in the figure, otherwise
it is of the same design. The same will swing a diameter of about
inches over the shaft. The motor, and the resistance and capacity
on boxes, are mounted on the
extended cabinet top of the
end of the motor. The motor
shaft is connected to the
to the shaft of the motor
The motor is mounted on the


ing at the back of the headstock. The speed changes are secured



[illegible]


lengthwise to engage with their respective gears on the driving sleeve.

The lathe is provided with an attachment for cutting tapers, (see illustration). It is set for tapers by loosening the cross-feed screw and tightening the screw in the sliding block and in the dog. It may be instantly changed to turn straight by loosening the screw in the dog.



Two Views of the Compound Rest and Taper Attachment.

The bushings for the back gear shaft are placed at either end and are provided with oil reservoirs for self lubrication. In the center of the bearings for the spindle and driving sleeve, deep oil



Lodge and Shipley Patent Main Bearing

wells are cast, these are connected with gauge glasses at the front of the headstock, so the height of the oil in the reservoirs can always be seen.

At the center of each bearing is fastened a brass ring with four projections, these projections act as buckets and pour the oil on the bearings.

The tail stock is very solidly built and has a long bearing on the bed. It is shaped so as to allow the compound rest to be set

the following is a list of the various methods of

the same.

The table is provided with an attachment for holding the
(see illustration). It is set for use by loosening the
Feed screw and tightening the screw in the sliding block and in the
dog. It may be instantly changed to turn screws by loosening the
screw in the dog.


The bearings for the shaft are made of steel and
are provided with all necessary for self lubrication. In the
center of the bearings for the shaft and having a diameter of
which are cast. These are con-
nected with a large screw at
the front of the machine.
The height of the oil in the
reservoir can always be seen.

In the center of each bearing is fastened a small ring with four
projections, these projections are in contact and form the oil seal.

Fig. 1.

The cast steel is very solid and has a long bearing
life. It is fitted so as to allow the oil to flow freely.


at 90 degrees when using the tool on small diameters. Suitable




Tail Stock Rest

The range of feeds is very flexible. At the bottom of each column of the index plate is given the minimum and maximum feeds obtainable when the pointer is in that column. Intermediate speeds are secured by placing the knob in the holes indicated. The ratio of the feeds to the threads is two to one.


See the next page for the blue print of the table showing the various feeds or threads obtainable per inch.




16" Lathe Compound Tool Rest



POSITION OF KNURLED GEAR WHEN CUTTING EXTRA THREADS. THE DOTTED LINES SHOW THE POSITION WHEN CUTTING THE REGULAR THREADS OF INDEX.



ARRANGEMENT OF SAME GEAR TO CUT EXTRA-COARSE THREADS



TO CUT EXTRA-FINE THREADS

at 60 degrees when using the foot on each specimen. The results

showed that the results are similar on the two

specimens to be tested over the whole

work and the results are as follows:

index increased to sixteenth of

an inch.

The range of loads is very flexible.

At the bottom of each column of the in-

ter space is given the minimum and maximum

loads. The results of the tests are in that column. The results

are given in the column by giving the load in the column and the

The ratio of the loads to the results is two to one.

See the next page for the line print of the table showing the

various loads or results of the tests.

Feed Index for Cutting Threads.

Thds. Knob	Thds. Knob	Thds. Knob	Thds. Knob	Thds. Knob
36 2	18 2	9 2	4 2	2 2
38 3	19 3	9.5 3	4.5 3	2.25 3
40 4	20 4	10 4	4.75 4	2 3/8 4
44 5	22 5	11 5	5 5	2 1/2 5
46 6	23 6	11.5 6	5.5 6	2 3/4 6
48 7	24 7	12 7	6 7	3 7
52 8	26 8	13 8	6.5 8	3 1/4 8
56 9	28 9	14 9	7 9	3 1/2 9
60 10	30 10	15 10	7.5 10	3.75 10
64 11	32 11	16 11	8 11	4.0 11
F E E D S				
128 to 72	64 to 36	32 to 18	16 to 8	8 to 4

Lodge and Shipley 16" patent head high speed lathe.

Calibration of the Controller

We went to considerable trouble in order to calibrate the handle on the controller so that any one of the ten notches in the controller box could be secured as desired.

Good index for coloring 'household'.

Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099
1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	

136 fo 78 7S 84 fo 90 96 9S 99 100 101 102 103 104

orange and shirley 10" patent head high speed 12 lbs.

Calibration of the control

control box could be secured as desired.

TABLE of SPEEDS and GEARS.


2 1/2 H.P. Northern variable speed motor: current, 20 amps
volts, 110: R.P.M., 500-1000: No. 16603.

Lodge and Shipley 16 in. patent head lathe.

The following table shows the actual lathe speeds at
rated load of motor:-

GEARS	R. P. M.	DIRECT DRIVE	BACK GEARS	GEARS ON MOTOR SHAFT
1	0-26	out	2	AB
2	26-54	out	2	CD
3	40-84	out	1	AB
4	84-170	out	1	CD
5	122-260	in	out	AB
6	260-510	in	out	CD

For other speeds see efficiency tables.



Change Gears on 16" Lodge and Shipley High Speed Lathe.

TABLE of SPEEDS and GEAR.

2 V.M. Motor Variable Speed Motor Current 20 to 100 A.M.P. 200-10000 H.P. 10000.

odge and Chisley to the patent head table.

The following table shows the actual table speeds at

rated load of motor:-

Speed	R.P.M.	Direct	Reverse	Motor Shaft
1	30-20	out	in	10
2	40-30	out	in	20
3	50-35	out	in	30
4	60-40	out	in	40
5	70-45	in	out	50
6	80-50	in	out	60

for other speeds see efficiency table.



Photograph showing lathe in readiness for efficiency tests
with Prony brake in place.

characterized by a high degree of efficiency and

the very best of kind.

EFFICIENCY TEST OF THE LATHE.

The object of the test was to determine the combined efficiency of the lathe and motor for various speeds and loads.

The results of the test are given in tables 1-6 and curve sheets 1-12 on the following pages.

The wiring of the lathe motor for the test was done as shown in the figure of electrical connections. A direct current watt-meter was placed in the circuit and calibrated as described elsewhere in the thesis.

A 12-inch pulley, taken from the Pelton water wheel, was mounted with set screw on a 2-inch shaft 18 inches long, and placed between centers on the lathe. A "dog" was placed on the head stock end in the usual manner. The pulley carried a strap form of Prony brake (see photograph). The brake arm rested on a strut supported on platform scales. The scales were calibrated by means of U.S. Standard weights and found to be correct. The notch on the brake arm was made 31.52 inches from the center of the shaft so that the formula for Brake Horse Power (B.H.P.) would be simplified.

$$B.H.P. = \frac{2\pi N.P.}{33000} = \frac{2\pi 31.52xN.P.}{33000} = \frac{N.P}{2000}$$

where P = pressure on the scales minus the brake constant minus the weight of the strut, all in pounds. N = revolutions of pulley per minute.

The following method was pursued in conducting the brake tests. The watt-meter was connected up and placed in the position to give the correct reading when current was reversed in direction, by means

[illegible]

The object of the test is to detect the presence of drugs

of the late and color for various and to

The results of the test are given in table 1 and 2.

...on the following pages.

The wiring of the alarm motor for the bell was found as follows:

the figure of electrical connections; three current well -

is placed in the circuit and collapsed as before; otherwise it is

9. 1994

18-inch and ev. taken from the 18-inch well.

Reported with few or no signs of disease and no signs of disease

between conflicts on the table. "John" was placed on the next block.

10-10-68

Take care not to make any mistake. The plates are placed on a special support.

[illegible]

100-443887-1000

— 203 —

3. For people born over 1911, you do not need to fill in

... ..

where ρ is the pressure on the walls and the prime denotes

The weight of the stone is 100 lbs.

Address: _____

1948 1949 1950 1951 1952 1953 1954 1955 1956 1957 1958 1959 1960 1961 1962 1963 1964 1965 1966 1967 1968 1969 1970 1971 1972 1973 1974 1975 1976 1977 1978 1979 1980 1981 1982 1983 1984 1985 1986 1987 1988 1989 1990 1991 1992 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 2577 2578 2579 2580 2581 2582 2583 2584 2585 2586 2587 2588 2589 2590 2591 2592 2593 2594 2595 2596 2597 2598 2599 2600 2601 2602 2603 2604 2605 2606 2607 2608 2609 2610 2611 2612 2613 2614 2615 2616 2617 2618 2619 2620 2621 2622 2623 2624 2625 2626 2627 2628 2629 2630 2631 2632 2633 2634 2635 2636 2637 2638 2639 2640 2641 2642 2643 2644 2645 2646 2647 2648 2649 2650 2651 2652 2653 2654 2655 2656 2657 2658 2659 2660 2661 2662 2663 2664 2665 2666 2667 2668 2669 2670 2671 2672 2673 2674 2675 2676 2677 2678 2679 2680 2681 2682 2683 2684 2685 2686 2687 2688 2689 2690 2691 2692 2693 2694 2695 2696 2697 2698 2699 2700 2701 2702 2703 2704 2705 2706 2707 2708 2709 2710 2711 2712 2713 2714 2715 2716 2717 2718 2719 2720 2721 2722 2723 2724 2725 2726 2727 2728 2729 2730 2731 2732 2733 2734 2735 2736 2737 2738 2739 2740 2741 2742 2743 2744 2745 2746 2747 2748 2749 2750 2751 2752 2753 2754 2755 2756 2757 2758 2759 2760 2761 2762 2763 2764 2765 2766

...well-known was connected as and placed in the position to give


2001-2002, 2003-2004, 2005-2006, 2007-2008, 2009-2010, 2011-2012, 2013-2014, 2015-2016, 2017-2018, 2019-2020, 2021-2022, 2023-2024, 2025-2026, 2027-2028, 2029-2030, 2031-2032, 2033-2034, 2035-2036, 2037-2038, 2039-2040, 2041-2042, 2043-2044, 2045-2046, 2047-2048, 2049-2050, 2051-2052, 2053-2054, 2055-2056, 2057-2058, 2059-2060, 2061-2062, 2063-2064, 2065-2066, 2067-2068, 2069-2070, 2071-2072, 2073-2074, 2075-2076, 2077-2078, 2079-2080, 2081-2082, 2083-2084, 2085-2086, 2087-2088, 2089-2090, 2091-2092, 2093-2094, 2095-2096, 2097-2098, 2099-2100, 2101-2102, 2103-2104, 2105-2106, 2107-2108, 2109-2110, 2111-2112, 2113-2114, 2115-2116, 2117-2118, 2119-2120, 2121-2122, 2123-2124, 2125-2126, 2127-2128, 2129-2130, 2131-2132, 2133-2134, 2135-2136, 2137-2138, 2139-2140, 2141-2142, 2143-2144, 2145-2146, 2147-2148, 2149-2150, 2151-2152, 2153-2154, 2155-2156, 2157-2158, 2159-2160, 2161-2162, 2163-2164, 2165-2166, 2167-2168, 2169-2170, 2171-2172, 2173-2174, 2175-2176, 2177-2178, 2179-2180, 2181-2182, 2183-2184, 2185-2186, 2187-2188, 2189-2190, 2191-2192, 2193-2194, 2195-2196, 2197-2198, 2199-2200, 2201-2202, 2203-2204, 2205-2206, 2207-2208, 2209-2210, 2211-2212, 2213-2214, 2215-2216, 2217-2218, 2219-2220, 2221-2222, 2223-2224, 2225-2226, 2227-2228, 2229-2230, 2231-2232, 2233-2234, 2235-2236, 2237-2238, 2239-2240, 2241-2242, 2243-2244, 2245-2246, 2247-2248, 2249-2250, 2251-2252, 2253-2254, 2255-2256, 2257-2258, 2259-2260, 2261-2262, 2263-2264, 2265-2266, 2267-2268, 2269-2270, 2271-2272, 2273-2274, 2275-2276, 2277-2278, 2279-2280, 2281-2282, 2283-2284, 2285-2286, 2287-2288, 2289-2290, 2291-2292, 2293-2294, 2295-2296, 2297-2298, 2299-2300, 2301-2302, 2303-2304, 2305-2306, 2307-2308, 2309-2310, 2311-2312, 2313-2314, 2315-2316, 2317-2318, 2319-2320, 2321-2322, 2323-2324, 2325-2326, 2327-2328, 2329-2330, 2331-2332, 2333-2334, 2335-2336, 2337-2338, 2339-2340, 2341-2342, 2343-2344, 2345-2346, 2347-2348, 2349-2350, 2351-2352, 2353-2354, 2355-2356, 2357-2358, 2359-2360, 2361-2362, 2363-2364, 2365-2366, 2367-2368, 2369-2370, 2371-2372, 2373-2374, 2375-2376, 2377-2378, 2379-2380, 2381-2382, 2383-2384, 2385-2386, 2387-2388, 2389-2390, 2391-2392, 2393-2394, 2395-2396, 2397-2398, 2399-2400, 2401-2402, 2403-2404, 2405-2406, 2407-2408, 2409-2410, 2411-2412, 2413-2414, 2415-2416, 2417-2418, 2419-2420, 2421-2422, 2423-2424, 2425-2426, 2427-2428, 2429-2430, 2431-2432, 2433-2434, 2435-2436, 2437-2438, 2439-2440, 2441-2442, 2443-2444, 2445-2446, 2447-2448, 2449-2450, 2451-2452, 2453-2454, 2455-2456, 2457-2458, 2459-2460, 2461-2462, 2463-2464, 2465-2466, 2467-2468, 2469-2470, 2471-2472, 2473-2474, 2475-2476, 2477-2478, 2479-2480, 2481-2482, 2483-2484, 2485-2486, 2487-2488, 2489-2490, 2491-2492, 2493-2494, 2495-2496, 2497-2498, 2499-2500, 2501-2502, 2503-2504, 2505-2506, 2507-2508, 2509-2510, 2511-2512, 2513-2514, 2515-2516, 2517-2518, 2519-2520, 2521-2522, 2523-2524, 2525-2526, 2527-2528, 2529-2530, 2531-2532, 2533-2534, 2535-2536, 2537-2538, 2539-2540, 2541-2542, 2543-2544, 2545-2546, 2547-2548, 2549-2550, 2551-2552, 2553-2554, 2555-2556, 2557-2558, 2559-2560, 2561-2562, 2563-2564, 2565-2566, 2567-2568, 2569-2570, 2571-2572, 2573-2574, 2575-2576, 2577-2578, 2579-2580, 2581-2582, 2583-2584, 2585-2586, 2587-2588, 2589-2590, 2591-2592, 2593-2594, 2595-2596, 2597-2598, 2599-2600, 2601-2602, 2603-2604, 2605-2606, 2607-2608, 2609-2610, 2611-2612, 2613-2614, 2615-2616, 2617-2618, 2619-2620, 2621-2622, 2623-2624, 2625-2626, 2627-2628, 2629-2630, 2631-2632, 2633-2634, 2635-2636, 2637-2638, 2639-2640, 2641-2642, 2643-2644, 2645-2646, 2647-2648, 2649-2650, 2651-2652, 2653-2654, 2655-2656, 2657-2658, 2659-2660, 2661-2662, 2663-2664, 2665-2666, 2667-2668, 2669-2670, 2671-2672, 2673-2674, 2675-2676, 2677-2678, 2679-2680, 2681-2682, 2683-2684, 2685-2686, 2687-2688, 2689-2690, 2691-2692, 2693-2694, 2695-2696, 2697-2698, 2699-2700, 2701-2702, 2703-2704, 2705-2706, 2707-2708, 2709-2710, 2711-2712, 2713-2714, 2715-2716, 2717-2718, 2719-2720, 2721-2722, 2723-2724, 2725-2726, 2727-2728, 2729-2730, 2731-2732, 2733-2734, 2735-2736, 2737-2738, 2739-2740, 2741-2742, 2743-2744, 27

A.I.T. May 10, 1906

Fred Norwood Wilson.

Charles B. Haycox

Diagram of Electrical Connections for Thesis Work



of the double^{throw} switch. A piece of pork was used for a lubricant on the brake, and^{grease} on the tail-stock point. As the brake heated up it was necessary to loosen the tail-stock so as to allow for the expansion of^{the} pulley shaft.

A series of 280 runs were made, varying the brake load for each of 36 different spindle speeds. The following readings were taken for each run: (1) revolutions per minute of spindle-using speed counter; (2) watt-meter reading in kilowatts; (3) gross pounds on platform scales; (4) number of gears and controller used.

ELECTRICAL CONNECTIONS.

The manner of connecting up the electrical apparatus is shown in the accompanying figure. The watt-meter used was calibrated each day by reversing the direction of the current through the motor armature and field, (this did not change the direction of rotation of the motor) and through the watt-meter. The position of the watt-meter with respect to the earth's field was varied and a bar magnet, made of hardened soft steel, and magnetized, was placed about 1 1/2 feet from the watt-meter. The poles of the magnet were reversed with respect to the earth's poles, and the position of the magnet was parallel to the earth's field. The distance of the magnet from the watt-meter was varied until on reversing the current the reading of the watt-meter remained unchanged. The reversal of current was obtained by means of a double throw switch fastened by set screws to the side of the lathe.

LODGE and SHIPLEY "HIGH SPEED" LATHE		2 1/2 H.P. - NORTHERN MOTOR		RESULTS of EFFICIENCY TEST of 16" LATHE								TABLE I	
Gears Controller		RPM	Proxy Brake Gross Pounds	Proxy Brake Net or P. Pounds	Motor Input K.W.	Input E.H.P.	Output B.H.P.	H.P. Loss	Efficiency B.H.P.-E.H.P.				
LODGE and SHIPLEY "HIGH SPEED" LATHE	1-1	14	16.6	0.4	0.34	0.45	0.001	0.45	0.3	Radius of Brake Arm - 31.52 inches Proxy Brake Constant = 16.2 lbs. B.H.P. = $\frac{P.N.}{2000}$	CHARLES C. CLAYTON Fred Hornwood Watson		
		14	85.1	68.9	0.80	1.07	0.48	0.58	45.0				
		14	141.0	124.8	1.17	1.57	0.87	0.70	55.5				
		13	160.5	144.3	1.32	1.77	0.93	0.81	53.0				
	1-2	13	161.0	144.8	1.35	1.81	0.94	0.87	52.0				
		15	16.6	0.4	0.30	0.40	0.001	0.40	0.3				
		15	70.0	53.8	0.67	0.90	0.40	0.49	45.0				
		16	111.5	95.3	1.02	1.37	0.76	0.60	55.5				
		16	151.0	134.8	1.37	1.84	0.87	0.96	47.5				
	1-3	18	16.6	0.4	0.34	0.45	0.003	0.45	0.8				
		18	50.0	33.8	0.62	0.83	0.30	0.52	36.5				
		18	94.2	78.0	0.97	1.30	0.70	0.60	54.0				
		18	124.0	107.8	1.32	1.77	0.97	0.80	55.0				
		17.8	137.0	120.8	1.45	1.94	1.07	0.87	55.0				
		17.7	135.0	118.8	1.82	2.44	1.41	1.03	56.0				
	1-4	22	16.7	0.5	0.32	0.43	0.005	0.43	1.2				
		22	57.5	41.3	0.72	0.97	0.45	0.51	42.0				
		21.7	103.5	87.3	1.27	1.71	0.94	0.76	55.5				
		21.5	130.5	114.3	1.57	2.10	1.23	0.87	58.5				
		21.0	153.0	136.8	1.81	2.42	1.43	1.00	59.0				
		21.0	172.0	155.8	2.09	2.73	1.79	0.84	65.5				
1-5	24.1	16.7	0.5	0.35	0.47	0.006	0.46	1.2					
	24.0	36.0	19.8	0.55	0.73	0.237	0.50	32.0					
	24	94.0	22.8	0.66	0.88	0.33	0.55	37.5					
	24	76.7	60.5	1.07	1.43	0.72	0.71	50.5					
	24	102.9	86.2	1.40	1.87	1.03	0.84	55.0					
	24	134.5	118.3	1.82	2.44	1.92	1.02	58.0					
	24	165.0	148.8	2.22	2.98	1.78	1.20	60.0					
	24	173.0	158.8	2.33	3.12	1.88	1.24	60.0					
1-6	30	16.6	0.4	0.37	0.49	0.006	0.49	1.2					
	30	30.5	14.3	0.57	0.76	0.21	0.55	28.0					
	30	49.2	33.0	0.82	1.10	0.49	0.60	45.0					
	29	59.3	43.1	0.97	1.30	0.62	0.67	48.0					
	28	89.0	72.8	1.39	1.86	1.02	0.84	55.0					
	27	110.0	94.8	1.70	2.28	1.28	1.0	56.0					
	26	138.0	121.8	2.12	2.85	1.58	1.27	55.5					

Charles C. Shayer
Fred Howard Wilson

THESIS

MAY 25, 1906

ARMOUR INSTITUTE OF TECHNOLOGY



RESULTS of EFFICIENCY TEST of 16" LATHE

TABLE II

Gears Controller	(N) RPM	Frany Brake Gross Pounds	Frany Brake Net Pounds	Motor Input A.W.	Input E.H.P.	Output B.H.P.	H.P. Loss	Efficiency in %			
2-1	30	16.2	0.4	0.45	0.60	0.005	0.59	1.0			
	28	70.0	53.8	1.12	1.50	0.25	0.74	50.0			
	27	100.0	89.8	1.60	2.14	1.21	0.92	56.5			
	26	100.0	122.8	2.07	2.28	1.60	0.98	57.5			
	25	161.5	145.3	2.40	3.22	1.81	1.40	58.5			
	24	169.0	152.8	2.50	3.35	1.83	1.51	55.0			
2-2	28	16.5	0.9	0.42	0.56	0.009	0.56	0.7			
	30	59.5	38.3	0.94	1.26	0.57	0.68	45.5			
	28	101.5	85.3	1.60	2.14	1.19	0.94	55.5			
	28	135.0	118.8	2.10	2.82	1.66	1.15	59.0			
	26	162.4	146.2	2.50	3.35	1.96	1.45	56.5			
	26	172.0	155.8	2.65	3.55	2.02	1.52	57.0			
2-3	36	12.7	0.5	0.46	0.61	0.01	0.60	1.4			
	35	60.0	43.8	1.06	1.39	0.76	0.57	57.0			
	34	85.0	68.8	1.61	2.16	1.17	0.99	57.0			
	33	115.0	98.8	2.10	2.81	1.63	1.18	58.0			
	33	123.5	126.3	2.60	3.48	2.02	1.46	58.0			
	31	163.0	146.8	3.00	4.02	2.27	1.74	56.5			
	32	174.0	159.8	3.22	4.32	2.52	1.79	58.5			
2-4	42	16.0	0.4	0.52	0.70	0.008	0.69	1.1			
	42	51.5	25.3	0.96	1.38	0.53	0.25	41.5			
	43	71.0	54.8	1.57	2.11	1.18	0.93	56.0			
	40	99.0	82.8	2.14	2.86	1.65	1.21	58.0			
	39	113.5	97.3	2.45	3.28	1.90	1.38	58.0			
	38	147.0	130.8	3.22	4.32	2.48	1.84	57.0			
	37	162.5	146.3	3.62	4.85	2.71	2.14	56.0			
2-5	53	16.0	0.4	0.54	0.72	0.01	0.71	1.3			
	46	36.0	19.8	0.86	1.28	0.47	0.81	37.0			
	30	53.5	39.3	1.42	1.90	0.59	1.31	31.0			
	46	78.0	61.8	1.96	2.62	1.42	1.20	54.0			
	46	91.5	75.3	2.60	3.48	1.73	1.75	50.0			
	46	121.0	104.0	3.05	4.09	2.41	1.68	59.0			
	49	136.0	119.8	3.97	5.65	2.64	2.91	56.5			
2-6	60	16.4	0.2	0.80	0.80	0.005	0.80	0.7			
	61	29.4	13.2	0.92	1.20	0.49	0.84	32.5			
	54	50.9	34.2	1.59	2.00	0.92	1.07	46.0			
	54	73.0	57.4	2.12	2.85	1.55	1.30	54.5			
	51	103.3	87.1	3.00	4.02	2.22	1.80	55.0			
	49	120.5	104.3	3.55	4.75	2.56	2.19	52.0			

P.N.
2000

Radius of Brake Arm - 31.52 inches

Frany Brake Constant - 16.2 lbs.

Charles C. Haynes
Fred Norwood Wilson

THESIS

MAY 25, 1906

ARMOUR INSTITUTE OF TECHNOLOGY

2 1/2 E.H.P.-NORTHERN MOTOR
LODGE and SHIPLEY "HIGH SPEED" LATHE

RESULTS of EFFICIENCY TEST of 16" LATHE

TABLE
III

GEARS CONTROLLER	N RPM	Pony Brake Gears Pounds	Pony Brake Net Pounds	Motor Input H.P.	Input E.H.P.	Output B.H.P.	H.P. Loss	Efficiency %			
3-1	42	16.0	0.4	0.33	0.44	0.008	0.43	1.9			
	42	52.2	26.0	1.00	1.34	0.75	0.58	57.5			
	41	82.0	65.8	1.63	2.18	1.35	0.83	62.0			
	40	96.5	80.3	1.93	2.58	1.61	0.97	62.5			
	39	120.0	103.8	2.47	3.32	2.02	1.30	61.0			
	37	137.2	121.0	2.92	3.92	2.24	1.68	57.0			
	37	150.2	134.0	3.30	4.42	2.47	1.95	56.0			
3-2	50	16.6	0.4	0.32	0.43	0.01	0.42	2.3			
	49	59.4	38.2	1.09	1.46	0.84	0.62	57.5			
	43	72.3	56.1	1.52	2.03	1.20	0.83	58.5			
	43	85.0	78.8	2.03	2.72	1.69	1.03	62.0			
	41.5	114.5	98.3	2.57	3.41	2.03	1.37	60.0			
	42	140.7	124.5	3.22	4.32	2.62	1.70	60.5			
	42	153.0	136.8	3.52	4.71	2.87	1.84	61.0			
3-3	56	18.5	0.3	0.35	0.47	0.008	0.46	1.8			
	56	42.0	25.8	1.00	1.34	0.75	0.59	56.0			
	52	67.4	51.2	1.67	2.25	1.33	0.92	59.0			
	59	82.0	70.8	2.22	2.97	1.91	1.06	64.0			
	50	110.0	93.8	2.84	3.81	2.39	1.42	61.5			
	47	127.6	111.4	3.40	4.55	2.62	1.93	57.5			
3-4	66	16.5	0.3	0.37	0.50	0.01	0.49	1.9			
	63	34.0	22.8	1.05	1.47	0.72	0.75	49.0			
	69	58.2	42.0	1.64	2.19	1.34	0.85	61.0			
	62	78.7	62.5	2.28	3.06	1.94	1.12	63.5			
	60	90.0	73.8	2.65	3.55	2.22	1.33	62.5			
	57	105.0	88.8	3.15	4.22	2.52	1.70	60.0			
	56	126.1	102.8	3.97	5.31	3.07	2.24	58.0			
3-5	80	16.5	0.2	0.43	0.57	0.01	0.56	2.08			
	76	33.3	17.1	1.02	1.37	0.85	0.72	47.0			
	79	58.0	41.8	1.83	2.53	1.65	0.87	65.0			
	70	78.0	61.8	2.60	3.47	2.17	1.30	62.5			
	66	91.6	75.9	3.27	4.37	2.49	1.88	57.0			
	68	99.0	82.8	3.60	4.82	2.81	2.01	56.5			
3-6	90	12.0	0.8	0.57	0.69	0.04	0.64	8.6			
	88	28.3	12.1	0.92	1.23	0.53	0.70	43.0			
	84	42.8	31.0	1.64	2.19	1.32	0.86	60.5			
	83	56.0	39.8	1.92	2.58	1.65	0.93	64.0			
	80	77.0	50.8	2.62	3.76	2.03	1.73	53.5			
	76	87.0	70.8	3.20	4.29	2.78	1.55	63.5			
	75	112.0	95.8	4.50	6.03	3.58	2.44	59.5			

Radius of Brake Arm - 31.52 inches B.H.P. - P.N. - 2000

Radius of Brake Arm - 16.2 lbs.

Pony Brake Constant - 16.2 lbs.

THESIS

MAY 25, 1906

ARMOUR INSTITUTE OF TECHNOLOGY

Charles G. Hager
Fred Woodward-Wilcox



RESULTS of EFFICIENCY TEST of 16" LATHE

Lodge and Shipley "High Speed" Lathe	Gears- Controller	N RPM	Frany Brake Gross Pounds	Frany Brake Net Pounds	Motor Input K.W.	Input EHP	Output B.H.P.	HP Loss	Effici- ency %	Frany Brake Constant-16.2 lbs.	Radius of Brake Arm-31.52 inches	B.H.P. 2000	TABLE IV
2 1/2 E.H.P. "NORTHERN" MOTOR	4-1	30	16.6	0.4	0.47	0.63	0.01	0.61	2.8				
		35	44.4	38.2	1.51	2.02	1.19	0.82	58.5				
		40	58.5	43.3	2.12	2.89	1.78	1.09	62.5				
		45	70.0	53.8	2.59	3.41	2.15	1.26	63.0				
		50	78.4	62.2	2.80	3.88	2.42	1.46	62.5				
		55	86.0	70.8	3.07	4.01	2.67	1.09	58.5				
2 1/2 E.H.P. "NORTHERN" MOTOR	4-2	30	16.6	0.4	0.47	0.63	0.01	0.61	2.8				
		35	33.6	17.4	1.12	1.50	0.78	0.72	52.0				
		40	46.4	30.2	1.65	2.21	1.35	0.86	61.0				
		45	54.2	38.0	1.98	2.65	1.71	0.94	64.5				
		50	70.0	53.8	2.07	3.52	2.26	1.26	64.5				
		55	83.0	66.8	3.25	4.35	2.83	1.51	65.0				
2 1/2 E.H.P. "NORTHERN" MOTOR	4-3	30	16.6	0.4	0.51	0.68	0.02	0.66	3.4				
		35	28.0	11.8	1.05	1.40	0.67	0.73	48.0				
		40	38.6	22.4	1.80	2.14	1.23	0.91	57.5				
		45	47.7	31.5	2.07	2.77	1.61	1.16	58.0				
		50	56.3	40.1	2.52	3.37	2.02	1.35	60.0				
		55	66.2	50.0	3.02	4.05	2.40	1.65	59.0				
2 1/2 E.H.P. "NORTHERN" MOTOR	4-4	30	16.6	0.4	0.67	0.89	0.02	0.87	2.8				
		35	25.5	9.3	1.21	1.62	0.59	1.03	36.5				
		40	32.9	16.7	1.65	2.21	1.07	1.14	48.5				
		45	38.6	22.4	2.02	2.70	1.34	1.34	50.0				
		50	51.2	35.0	2.76	3.70	2.06	1.64	55.5				
		55	56.7	40.5	3.20	4.28	2.39	1.89	56.0				
2 1/2 E.H.P. "NORTHERN" MOTOR	4-5	30	16.6	0.4	0.77	1.03	0.02	1.00	2.8				
		35	24.2	8.0	1.23	1.64	0.61	1.03	37.0				
		40	29.3	13.1	1.52	2.04	0.96	1.07	45.5				
		45	39.4	23.2	2.15	2.87	1.55	1.28	55.5				
		50	45.3	29.1	2.57	3.95	2.07	1.38	60.0				
		55	60.0	44.4	3.73	5.00	3.02	2.18	56.5				
2 1/2 E.H.P. "NORTHERN" MOTOR	4-6	30	16.6	0.4	0.85	1.14	0.03	1.10	3.1				
		35	20.2	4.0	1.16	1.55	0.33	1.22	21.5				
		40	27.1	10.9	1.67	2.23	0.94	1.29	42.0				
		45	36.9	20.2	2.37	3.18	1.72	1.46	54.0				
		50	43.5	27.3	2.97	3.98	2.11	1.88	59.0				
		55	51.5	35.3	3.62	4.85	2.62	2.23	54.0				

Charles G. Stacey
Fred Woodward

THESIS

ARMOUR INSTITUTE OF TECHNOLOGY - MAY 25, 1906



RESULTS of EFFICIENCY TEST of 16" LATHE

Gear 5 Controller	N	RPM	Frany Brake Gross Pounds	Frany Brake Net Pounds	Motor Input H.P.	Input E.H.P.	Output B.H.P.	H.P. Loss	Efficiency %			
5-1	133	16.8	0.6	0.44	0.59	0.04	0.55	6.7				
	126	28.0	11.8	1.05	1.41	0.74	0.67	52.5				
	122	37.6	21.4	1.60	2.14	1.30	0.78	60.5				
	123	43.7	27.5	2.04	2.74	1.69	1.05	61.5				
	126	51.9	35.7	2.56	3.42	2.25	1.17	65.5				
	116	57.0	40.8	2.95	3.95	2.37	1.58	60.0				
	110	66.0	48.8	3.62	4.85	2.74	2.11	57.5				
5-2	150	16.8	0.7	0.45	0.60	0.05	0.55	8.7				
	146	31.0	14.8	1.36	1.82	1.08	0.74	59.5				
	154	34.0	17.8	1.58	2.12	1.37	0.75	64.5				
	154	38.3	23.1	1.92	2.57	1.70	0.87	66.0				
	146	47.2	31.0	2.59	3.47	2.26	1.21	65.0				
	138	51.0	34.8	2.93	3.93	2.41	1.52	61.5				
	130	56.9	40.7	3.42	4.57	2.64	1.93	58.0				
5-3	174	17.1	0.9	0.45	0.60	0.07	0.52	13.0				
	180	25.0	8.8	1.04	1.39	0.78	0.60	57.0				
	164	32.5	16.3	1.64	2.19	1.34	0.85	61.0				
	168	40.8	24.6	2.32	3.10	2.07	1.03	66.5				
	166	47.0	30.8	2.82	3.91	2.57	1.34	67.0				
	160	53.2	37.0	3.57	4.78	2.86	1.82	62.0				
5-4	214	16.8	0.6	0.45	0.60	0.06	0.54	10.7				
	186	25.1	8.9	1.17	1.57	0.87	0.70	55.5				
	203	31.7	15.5	1.80	2.41	1.57	0.84	65.0				
	192	41.5	25.3	2.67	3.57	2.43	1.14	68.0				
	180	48.0	31.8	3.40	4.55	2.86	1.69	63.0				
	172	52.4	36.2	3.95	5.29	3.11	2.18	59.0				
5-5	230	16.6	0.4	0.49	0.65	0.04	0.61	7.0				
	240	22.6	6.4	1.04	1.39	0.76	0.62	55.0				
	222	27.0	10.8	1.58	2.01	1.20	0.79	59.5				
	220	32.0	15.8	2.00	2.67	1.74	0.93	65.0				
	222	37.7	21.5	2.57	3.45	2.38	1.07	69.0				
	216	42.0	25.8	3.10	4.15	2.79	1.36	67.0				
5-6	294	16.7	0.5	0.59	0.79	0.07	0.62	9.2				
	284	23.0	6.8	1.32	1.77	0.96	0.81	54.5				
	264	30.1	13.9	2.15	2.87	1.77	1.10	61.5				
	264	34.8	18.6	2.72	3.65	2.46	1.19	67.5				
	256	39.7	23.5	3.40	4.55	2.77	1.78	61.0				
	236	42.9	26.7	3.95	5.29	3.16	2.13	60.0				

TABLE
VCharles C. Stoyes
Fred Woodward-Wilson

--THESIS--

ARMOUR INSTITUTE of TECHNOLOGY MAY 25, 1906

Radius of Brake Arm - 31.52 inches

Frany Brake Constant 16.2 lbs.

H.P. = $\frac{F \cdot V}{2000}$

2 1/2 E.H.P. NORTHERN MOTOR

LOGGE and SHIPLEY "HIGH SPEED" LATHE



LOGE and SHIPLEY "H" LATHE	2 1/2 E.H.P.-NORTHERN MOTOR	RESULTS of EFFICIENCY TEST of 16" LATHE							TABLE VI
		Gears Controller	N RPM	Prony Brake Gross Pounds	Prony Brake Net Pounds	Motor Input K.W.	Input E.H.P.	Output B.H.P.	
6-1			260	27.5	11.3	1.75	2.39	1.47	67.0
			254	31.7	15.5	2.27	3.09	1.97	65.0
			257	34.5	18.3	2.65	3.55	2.36	66.5
			240	36.4	20.2	3.05	4.08	2.42	66.5
			230	40.5	24.3	3.56	4.77	2.80	69.0
			216	46.0	29.8	4.50	6.03	3.22	62.0
6-2			290	16.6	0.3	0.5	0.67	0.43	65.0
			265	21.0	4.8	1.02	1.37	0.58	42.5
			288	24.5	8.3	1.45	1.99	1.10	61.5
			280	28.8	12.6	1.88	2.65	1.76	67.5
			270	33.0	16.8	2.50	3.35	2.27	68.0
			262	36.5	20.3	3.10	4.15	2.66	69.0
			240	44.5	28.3	4.15	5.56	3.40	39.0
6-3			390	16.9	0.7	0.57	0.74	0.12	16.0
			350	19.6	3.4	0.97	1.30	0.59	46.0
			398	22.5	6.3	1.40	1.87	1.18	59.0
			336	28.1	11.9	2.23	2.99	2.06	70.0
			320	30.2	14.0	2.65	3.42	2.24	65.5
			320	33.6	17.4	3.07	4.12	2.78	67.5
			300	35.5	19.3	3.59	4.75	2.89	63.0
6-4			420	16.7	0.5	0.65	0.87	0.10	12.0
			424	18.5	2.3	0.92	1.24	0.48	32.5
			418	21.6	5.4	1.52	2.03	1.13	55.5
			410	24.9	8.7	2.08	2.79	1.78	64.0
			392	27.7	11.5	2.65	3.55	2.15	60.5
			400	29.0	12.8	2.92	3.91	2.56	65.5
			350	34.4	18.2	3.95	5.30	3.18	60.0
6-5			460	16.7	0.5	0.67	0.89	0.11	12.8
			480	18.2	2.0	0.97	1.30	0.48	37.0
			453	20.9	4.7	1.52	2.03	1.06	57.0
			420	22.5	6.3	2.04	2.73	1.32	48.5
			416	26.0	9.8	2.60	3.48	2.04	58.5
			424	29.1	12.9	3.35	4.48	2.74	61.0
			400	32.3	16.1	4.06	5.43	3.22	59.5
6-6			574	16.8	0.6	0.77	1.03	0.17	16.7
			560	18.0	1.8	1.06	1.42	0.50	35.5
			512	20.7	4.5	1.68	2.35	1.15	51.0
			584	23.0	6.8	2.26	3.02	1.71	56.5
			484	25.4	9.2	2.93	3.93	2.22	56.5
			450	28.2	12.0	3.65	4.89	2.70	55.0

$$B.H.P. = \frac{P.N.}{2000}$$

Radius of Brake Arm - 31.52 inches.

Prony Brake Constant - 16.2 lbs.


Charles C. Haynes
Fred Woodward Wilson


THESIS

MAY 25, 1906


ARMOUR INSTITUTE OF TECHNOLOGY








RIGHT OF PUBLICATION, CHICAGO.




LUCAS & DITZLER CO. CHICAGO






























DISCUSSION of RESULTS of the EFFICIENCY

TEST on a 16" LATHE.

The tables (I-IV) give the results of the brake tests on the lathe for 36 different gear and controller changes. For each one of these 36 variations in the spindle speed, the tables show the performance of the lathe for a load variation on the motor of from 12% of rated load (2.5 H.P.) to 100% overload. At the spindle speeds below 30 R.P.M. we were unable to screw the brake up tight enough to get an overload on the motor. The combined efficiency of motor and lathe throughout the range is also given. Twelve curves were plotted using the results obtained.

Curve I shows the brake horse power that can be secured with any motor input in K.W. throughout the range.

Curves (II-VII) inclusive show the efficiency variation in per cent for any number of R.P.M. Each one of these curves is for a certain constant motor input in K.W.

$$\text{EFF.} = \frac{\text{Output in K.W.}}{\text{Motor input in K.W.}}$$

Curve	Input-K. W.	R. P. M.	Max. Eff. %
II	1	175	53
III	2	225	67
IV	2.50	235	69
V	3.0	265	67.3
VI	3.5	225	63
VII	4.0	400	60

Curves (VIII-XII) inclusive show the efficiency variation in per cent for any number of R.P.M. Each one of the curves is for a certain constant brake-horse-power output.

TABLE I

The tables (I-IV) give the results of the brake tests on the

for 50 different gear and controller changes. For each one

of these 50 variations in the electric supply, the results show the per-

formance of the motor for a load variation on the motor of from 25%

at rated load (2.5 H.P.) to 100% overload. At the variable speeds

below 50 H.P.M. we were unable to screw the brake up tight enough to

get an overload on the motor. The combined efficiency of motor and

brake throughout the range is also given. Twelve curves were plotted

using the results obtained.

Curve I shows the brake horse power that can be secured with

any motor rated in H.P. throughout the range.

Curves (II-VI) inclusive show the efficiency variation in

at any number of H.P.M. Each one of these curves is for

at constant motor load in H.P. (2.5 H.P. to 100% overload in H.P.)

Curve	Rated H.P.	H.P.M.	Max. Eff. %
I	1	100	25
II	2	200	67
III	2.5	250	68
IV	3.0	300	67.5
V	4.0	400	66
VI	5.0	500	65

Curves (VII-IX) inclusive show the efficiency variation in

at any number of H.P.M. Each one of the curves is for a

variable constant brake horse power output.

Curve	Output-B. H. P.	R. P. M.	Max. Eff. -%
VIII	0.5	150	48
IX	1.0	250	60.7
X	2.0	260	67.
XI	2.5	225	67.3
XII	3.0	200	64

The results show the highest efficiency for 69% at 34% overload on the motor. Taking a good value of 80% as the efficiency of the motor alone, that of the lathe at 34% overload would be 86.5%. The combined efficiency of both is 69%.

The controller on the lathe was calibrated so that by using the tables (I-VI) and the table of speeds and gears, it is possible, knowing the K.W. input, to set the lathe so as to secure within 2 R.P.M. of the actual number of revolutions, without using a speed counter or watch. In this manner the desired cutting speed for any piece of work can be obtained instantly without taking any trial cuts as is necessary using a Warner Outmeter.

The actual amount of power consumed or the efficiency of the lathe and motor within certain limits is not so important as the saving of time in machining. However the efficiency results secured are of value to the makers of lathe-motors and lathes. The tables (I-VI) would be of value in making tests on lathes, similar to the one used, to find the actual power required in cutting off metal. The proportioning of lathe parts to withstand the force acting on the tool is of great importance in the design of modern lathes.

Drive	Output-H.P.	Max. Eff.-%
VII	0.8	80
IX	1.0	80.5
X	2.0	87
II	2.5	87.5
III	2.0	84

The results show the highest efficiency for 60% at 200 over-
load on the motor. Taking a good value of 80% as the efficiency of
the motor alone, that of the lathe at 20% overload would be 60.5%.

The combined efficiency of both is 60%.

The controller on the lathe was calibrated so that by using
the tables (I-VI) and the scale of speeds and gears, it is possible
knowing the H.P. input, to set the lathe so as to secure within 2 H.P.
of the actual number of revolutions without using a speed counter or
watch. In this manner the desired cutting speed for any piece of work
can be obtained instantly without taking any trial cuts as is necessary
using a Warner cutter.

The actual amount of power consumed or the efficiency of the
lathe and motor within certain limits is not so important as the ex-
act of time in machining. However the efficiency results are given
and of value to the makers of lathe motors and lathes. The tables
(I-VI) would be of value in making tests on lathes, similar to the
one used, to find the actual power required in cutting off metal.

The proportioning of lathe parts to withstand the forces acting on the
tool is of great importance in the design of modern lathes.

PREPARATION of TEST PIECE for LATHE.

The cast iron test piece used in performing the tests on High Speed tool Steel is shown in the accompanying print and also in the photographs. The pattern was made in the pattern shop and four castings were cast in the foundry of ARMOUR INSTITUTE of TECHNOLOGY. Each one of these castings weighed 460 pounds. It was found necessary to place each test piece in the slotting machine to remove rough parts which necessitated considerable extra work. The ends of the test piece were centered by means of an electrically driven hand drill.


A special hook was made and placed in the ceiling above the lathe in order to support a block and tackle for handling the test pieces. Although the test piece used was very heavy the friction at the tail stock did not cause the bearing at that point to heat up appreciably.

A special chuck was machined in the slotter to hold the lugs on the headstock end of the test piece.

REPORT OF THE BOARD OF INVESTIGATION

The case from the case used in performing the tests on the
specimen tool shown in the accompanying print and also in the
photograph. The specimen was made in the pattern shop and four
castings were cast in the foundry of AMERICAN NATIONAL TOOL CO.
Each one of these castings weighed 20 pounds. It was found necessary
to place each cast piece in the slotting machine to remove rough work
which necessitated considerable extra work. The ends of the cast
pieces were centered by means of an electrically driven head drill.
A special hook was made and placed in the ceiling above the
table in order to support a block and tackle for handling the cast
pieces. Although the cast piece used was very heavy the friction
at the cable block did not cause the casting at that point to heat up
appreciably.

A special chuck was designed in the shop to hold the tool
on the neckstock end of the cast wheel.



Standard form of Test Piece for Tests of
"High Speed Tool Steel" on Cast Iron.

A.I.T. May 20, 1906

Fred Greenwood Wilson
Charles C. Hayes

DESCRIPTION of GRINDING MACHINE.

The tools were all uniformly ground on an electrically driven grinder made by the Gisholt Machine Co. The mechanism of the grinder is such that four different settings of a tool can be obtained, the angle of each setting being shown on a graduated scale. The carriage supporting the tool can be moved laterally by a hand wheel and brought up to the emery wheel by a lever. Running water is sprayed over the tool automatically while the grinder is in motion. The grinder is directly connected to a 5 H.P. motor. On the other end of the motor shaft is a small pulley carrying a 5/8 in. belt which runs over another pulley near the floor. The second pulley and shaft puts into action the device for supplying the spray of water. The same water is used over and over again. A starting box was placed on the wall near the grinder for permanent use.

The table was set on a level ground in an elevated position.

knives grinder made by the Electric Machine Co. The mechanism of the grinder is such that four different settings of a tool can be obtained. The angle of each setting being shown on a graduated scale. The carriage supporting the tool can be moved laterally by a hand wheel and brought up to the emery wheel by a lever. Running water is conveyed over the tool automatically while the grinder is in motion. The grinder is directly connected to a 2 H.P. motor. On the other end of the motor shaft is a small pulley carrying a 3/8 in. belt which runs over another pulley near the floor. The second pulley and shaft put into action the device for supplying the spray of water. The same water is used over and over again. A straining box was placed on the wall near the grinder for permanent use.

DESCRIPTION of the DRILL PRESS

used for the HARDNESS TESTS on CAST IRON.

In order to have a fair test of the HighSpeed Steel tools used, the cast iron test pieces, on which the cutting is done, should be referred to a certain standard of hardness. The hardness of iron affects the cutting speed more than any other quality, therefore, a comparative hardness test is quite necessary. In order to carry on this test a drill press, made by S.W.Putnam Sons, Pitchburg, Mass., was fitted up as follows: the hand-wheel rim was graduated by means of a milling machine so that the passage of one division of the scale by a fixed pointer indicated a travel of one-hundredth of an inch of depth of drill. The number of divisions necessary (420) was found by noting the travel of a point on the drill for one revolution of the hand-wheel. This distance was 4.20 inches. A device was attached to the lever of the drill press on which a weight of 50 pounds could be hung.

By means of this apparatus the comparative hardness of two or more pieces of metal may be found as follows. Adopt one piece of metal as the standard. In our tests we took a grey iron casting 2"x2"x12" made in the foundry of the ARMOUR INSTITUTE of TECHNOLOGY.

With the drill rotating at a constant speed the rate of feed of the drill in inches per minute is secured taking readings every 0.1 inch drilled. A Morse standard 1/2 inch drill is used in the test, ground to an angle of 60 degrees. As the sharpness of the drill is liable to vary, a short preliminary run is made on the standard test

REPORT OF THE COMMISSIONERS OF THE GENERAL LAND OFFICE
ON THE PROGRESS OF THE SURVEY OF THE LANDS OF THE
CROWN IN THE YEAR 1881

In order to have a fair test of the hardness of iron
used for the purpose of cutting, on which the cutting is done, should
be referred to a certain standard of hardness. The hardness of iron
affects the cutting speed more than any other quality. Therefore, a
comparative hardness test is quite necessary. In order to carry out
this test a drill press, made by J. W. Brown & Co., Liverpool, Eng.,
was fitted up as follows: the hand-wheel rim was graduated by means
of a milling machine so that the passage of one revolution of the handle
by a fixed pointer indicated a travel of one-hundredth of an inch of
feed of drill. The number of divisions necessary (430) was found by
noting the travel of a point on the drill for one revolution of the
hand-wheel. This distance was 0.23 inches. A device was attached
to the lever of the drill press on which a weight of 30 pounds could
be hung.

By means of this apparatus the comparative hardness of two
or more pieces of metal may be found as follows. About one piece
of metal as the standard. In our case we took a grey iron casting
"B" made in the foundry of the ARMOUR INSTITUTION OF TOWN, N.Y.

With the drill rotating at a constant speed the rate of feed
of the drill in inches per minute is secured taking readings every
0.1 inch drilled. A Morse standard 1/2 inch drill is used in the
test, ground to an angle of 60 degrees. In the sharpness of the drill
is liable to vary, a short preliminary run is made on the standard and



Photograph of drill press showing arrangement for hardness

test on cast iron specimen.

Figure IV

(Photograph of still from showing emergence of the dragon)

Text on last slide omitted.

Figure V

piece previous to each regular run. In this manner a comparison can always be obtained with a standard. The comparative hardness of the test piece is one hundred times the depth in inches drilled per minute in the standard specimen, divided by the depth in inches per minute drilled in the test piece. This is assuming one hundred as the hardness of the standard cast iron. The forgoing method was secured from a report written by Prof. J. T. Nicolson of the Manchester Municipal School of Technology, Manchester, England.

These provisions to each specimen were always be obtained with a standard. The comparative hardness of the test piece is one hundred times the depth in inches drilled per minute in the standard specimen, divided by the depth in inches per minute drilled in the test piece. This is assuming one standard as the hardness of the standard cast iron. The foregoing method was adopted from a report written by Prof. J. T. Nicholson of the Manchester Municipal School of Technology, Manchester, England.

Test of the HIGH SPEED STEEL TOOLS.

The test of the high speed steel tools on the cast iron specimens were conducted in the following manner: two tools from each of six different grades of steel were forged, hardened, and ground as described elsewhere in the thesis. The front clearance on the tools ($6^{\circ}10'$) was secured by hand on the emery wheel.

All tools were placed in the tool rest perpendicular to the center line of the work. The nose of the tool was adjusted from $1/8$ to $1/4$ " above the center line of the work. This was secured by means of a steel rule supported at the correct height above the ways on two blocks of wood placed on end.

Before starting the test all moving parts of the lathe were oiled. A wooden box 1'x1'x2' was made and placed under the lathe bed to catch the chips. All the cuttings removed during a run were swept up, placed in this box, and weighed on platform scales. Pieces of sheet metal were cut and put about the tool when in use so as to keep tool rest as clean as possible. In order to prevent slippage the set screw on the tool rest, and bolts on the carriage and on the tail stock were screwed up tightly.

The feed in inches per revolution was secured by means of the table on gears for thread cutting. The number of revolutions per inch of longitudinal travel of tool is two times the number of threads set. These feeds are accurate as we found by calibration.

The desired depth of cut was obtained by means of the graduated scale on the upper tool rest cross feed screw. The actual depth of cut was secured by finding the circumference of the test

The foot of the high speed steel on the cast iron specimens were contacted in the following manner: two tools from each of six different grades of steel were forged, hardened, and ground as described elsewhere in the thesis. The front clearance on the tools (Fig. 1) was secured by hand on the emery wheel. The tools were placed in the tool rest perpendicular to the center line of the work. The nose of the tool was adjusted from 1/4" to 1/2" above the center line of the work. This was secured by means of a steel rule supported at the correct height above the work on two blocks of wood placed on end. Before starting the test all moving parts of the lathe were oiled. A wooden box (Fig. 2) was made and placed under the lathe bed to catch the chips. All the cuttings removed during a run were swept up, placed in this box, and weighed on a platform scale. Pieces of sheet metal were cut and bent about the tool when in use so as to keep tool rest as clean as possible. In order to prevent vibration the rest screw on the tool rest, and bolts on the carriage and on the lathe block were renewed as frequently. The feed in inches per revolution was secured by means of the table on gears for direct cutting. The number of revolutions per inch of longitudinal travel of tool is two times the number of threads per inch. These feeds are accurate as we found by calibration. The desired depth of cut was obtained by means of the graduated scale on the upper tool rest cross feed screw. The actual feeds of cut were secured by finding the circumference of the test



Photograph showing lathe in readiness for a test of
HIGH SPEED STEEL on Cast Iron.

Photograph showing ledge in readiness for a test of

With same test on test run.

Relative Diameters, Speeds and Revolutions

Diameter	Feet per minute										
	15	20	25	30	35	40	45	50	60	70	80
	Revolutions per minute										
1/4	229	306	382	458	535	611	688	764	917	1070	1222
5/16	183	245	306	367	428	489	550	611	733	856	978
3/8	153	204	255	306	357	408	458	509	611	713	815
7/16	131	175	218	262	306	349	393	437	524	611	699
1/2	115	153	191	229	268	306	344	382	459	535	611
3/8	91.8	123	153	184	214	245	276	306	367	428	489
3/4	76.3	102	127	153	178	203	229	254	306	357	408
7/8	65.5	87.3	109	131	153	175	196	219	262	306	349
1	57.3	76.4	95.5	115	134	153	172	191	229	267	306
1 1/8	51	68	85	102	119	136	153	170	204	238	272
1 1/4	45.8	61.2	76.3	91.8	107	123	137	153	183	214	245
1 3/8	41.7	55.6	69.5	83.3	97.2	111	125	139	167	195	222
1 1/2	38.2	50.8	63.7	76.3	89.2	102	115	127	153	178	204
1 5/8	35	47	58	70.5	82.2	93.9	106	117	141	165	188
1 3/4	32.7	43.6	54.5	65.5	76.4	87.3	98.2	109	131	153	175
1 7/8	30.6	40.7	50.9	61.1	71.3	81.5	91.9	102	122	143	163
2	28.7	38.2	47.8	57.3	66.9	76.4	86	95.5	115	134	153
2 1/4	25.4	34	42.4	51	59.4	68	76.2	85	102	119	136
2 1/2	22.9	30.6	38.2	45.8	53.5	61.2	68.8	76.3	91.7	107	122
2 3/4	20.8	27.8	34.7	41.7	48.6	55.6	62.5	69.5	83.4	97.2	111
3	19.1	25.5	31.8	38.2	44.6	51	57.3	63.7	76.4	89.1	102
3 1/2	16.4	21.8	27.3	32.7	38.2	43.6	49.1	54.5	65.5	76.4	87.4
4	14.3	19.1	23.9	28.7	33.4	38.2	43	47.8	57.3	66.9	76.4
4 1/2	12.7	16.9	21.2	25.4	29.6	34	38.2	42.4	51	59.4	67.9
5	11.5	15.3	19.1	22.9	26.7	30.6	34.4	38.2	45.9	53.5	61.1
5 1/2	10.4	13.9	17.4	20.8	24.3	27.8	31.3	34.7	41.7	48.6	55.6
6	9.6	12.7	15.9	19.1	22.3	25.5	28.7	31.8	38.2	44.6	51
7	8.1	10.9	13.6	16.4	19.1	21.8	24.6	27.3	32.7	38.2	43.7
8	7.2	9.6	11.9	14.3	16.7	19.1	21.1	23.9	28.7	33.4	38.2
9	6.4	8.5	10.6	12.7	14.9	17	19.1	21.2	25.5	29.7	34
10	5.7	7.6	9.6	11.5	13.4	15.3	17.2	19.1	22.9	26.7	30.6
11	5.2	6.9	8.7	10.4	12.2	13.9	15.6	17.4	20.8	24.3	27.8
12	4.8	6.4	8	9.6	11.1	12.7	14.3	15.9	19.1	22.3	25.5
13	4.4	5.9	7.3	8.8	10.3	11.8	13.2	14.7	17.6	20.6	23.5
14	4.1	5.5	6.8	8.1	9.6	10.9	12.3	13.6	16.4	19.1	21.8
15	3.8	5.1	6.4	7.6	8.9	10.2	11.5	12.7	15.3	17.8	20.4
16	3.6	4.8	6	7.2	8.4	9.6	10.7	11.9	14.3	16.7	19.1
18	3.2	4.2	5.3	6.3	7.4	8.5	9.5	10.6	12.7	14.8	17
20	2.8	3.8	4.8	5.7	6.7	7.6	8.6	9.6	11.4	13.3	15.3
22	2.6	3.4	4.3	5.2	6.1	6.9	7.8	8.7	10.4	12.1	13.9
24	2.4	3.2	4	4.8	5.5	6.3	7.1	7.9	9.5	11.1	12.7



piece at three points before and after each run using a steel tape. Dividing the mean circumference by π and taking $1/2$ the difference between the diameters before and after the cut, gives the actual depth of cut. The revolutions per minute of the spindle to give the desired approximate cutting speed, ~~was~~^{were} secured as follows:

$$R. P. M. = \frac{\text{desired cutting speed in ft./min.} \times 3.82}{\text{diameter of work in inches}}$$

Referring to the tables of the efficiency test of the lathe and knowing by trial the power in K. W. required to take a certain cut, we were able to secure a certain gear change and controller notch that would give the desired R. P. M. of the spindle in order to secure a cutting speed of from 15 to 80 ft./min. on work of from $1/4$ inch to 24 inches in diameter. This table is very convenient but the formula was used for speeds greater than 80 ft./min.

The following data was taken during the test:

Brand and number of tool used.

Number of test,

Feed set in inches per revolution.

Cut set.

Mean circumference of work before run.

" " " " after "

Diameter of work before run.

" " " after "

Actual cut in inches.

R.P.M. by hand speed counter.

Duration of run in minutes.

Weight of iron removed in pounds.

pieces at three points before and after each run under a steel wheel
 dividing the mean circumference by and taking $\sqrt{3}$ the difference
 between the diameters before and after the run gives the actual loss
 of oil. The revolutions per minute of the spindle to give the de-

sired approximate cutting speed, was secured as follows:

$V.P.M. \times \text{Desired cutting speed in ft./min.} \times 3.82$
 diameter of work in inches

Referring to the tables of the efficiency test of the lathe and know-
 ing by trial the power in H.P. required to take a certain cut, we were
 able to secure a certain gear change and controller notch that would
 give the desired R.P.M. of the spindle in order to secure a cutting
 speed of from 15 to 30 ft./min. on work of from $\sqrt{4}$ inch to 32 inches
 in diameter. This table is very convenient but the formula was used
 for speeds greater than 30 ft./min.

The following data was taken during the test:

Brand and number of tool used.					
Number of test.					
Feed set in inches per revolution.					
Cut set.					
Mean circumference of work before run.					
" " " " " "	after	"	"	"	"
Diameter of work before run.					
" " " " " "	after	"	"	"	"
Actual cut in inches.					
R.P.M. by hand speed counter.					
Duration of run in minutes.					
Weight of iron removed in pounds.					

Number of gears and controller used.

K. W. from watt-meter--no load.

" " " " --with load.

Rake on tool-front to back.

" " " -side to side.

Clearance on tool-front.

" " " -side.

Angle between cutting edge, and side of tool.

Why run was stopped.

Condition of tool after run.

Number of temper on tool.

" " test piece.

The point of the tool was ground after its condition went below "good".

An "excellent" tool was one on which no perceptible change was noted on the cutting edge.

A "good" tool was one which showed no bad effects and could keep up the cut across the test piece (30") without the work showing any taper.

A "fair" tool was one which could keep up the cut across the test piece but left the work tapered.

A "failed" tool would not sustain the cut one-half the way across the test piece.

240 34 10000 104.0400 1.0000

1897-1898-1899-1900-1901-1902-1903-1904-1905-1906-1907-1908-1909-1910-1911-1912-1913-1914-1915-1916-1917-1918-1919-1920-1921-1922-1923-1924-1925-1926-1927-1928-1929-1930-1931-1932-1933-1934-1935-1936-1937-1938-1939-1940-1941-1942-1943-1944-1945-1946-1947-1948-1949-1950-1951-1952-1953-1954-1955-1956-1957-1958-1959-1960-1961-1962-1963-1964-1965-1966-1967-1968-1969-1970-1971-1972-1973-1974-1975-1976-1977-1978-1979-1980-1981-1982-1983-1984-1985-1986-1987-1988-1989-1990-1991-1992-1993-1994-1995-1996-1997-1998-1999-2000-2001-2002-2003-2004-2005-2006-2007-2008-2009-2010-2011-2012-2013-2014-2015-2016-2017-2018-2019-2020-2021-2022-2023-2024-2025-2026-2027-2028-2029-2030-2031-2032-2033-2034-2035-2036-2037-2038-2039-2040-2041-2042-2043-2044-2045-2046-2047-2048-2049-2050-2051-2052-2053-2054-2055-2056-2057-2058-2059-2060-2061-2062-2063-2064-2065-2066-2067-2068-2069-2070-2071-2072-2073-2074-2075-2076-2077-2078-2079-2080-2081-2082-2083-2084-2085-2086-2087-2088-2089-2090-2091-2092-2093-2094-2095-2096-2097-2098-2099-2100-2101-2102-2103-2104-2105-2106-2107-2108-2109-2110-2111-2112-2113-2114-2115-2116-2117-2118-2119-2120-2121-2122-2123-2124-2125-2126-2127-2128-2129-2130-2131-2132-2133-2134-2135-2136-2137-2138-2139-2140-2141-2142-2143-2144-2145-2146-2147-2148-2149-2150-2151-2152-2153-2154-2155-2156-2157-2158-2159-2160-2161-2162-2163-2164-2165-2166-2167-2168-2169-2170-2171-2172-2173-2174-2175-2176-2177-2178-2179-2180-2181-2182-2183-2184-2185-2186-2187-2188-2189-2190-2191-2192-2193-2194-2195-2196-2197-2198-2199-2200-2201-2202-2203-2204-2205-2206-2207-2208-2209-2210-2211-2212-2213-2214-2215-2216-2217-2218-2219-2220-2221-2222-2223-2224-2225-2226-2227-2228-2229-2230-2231-2232-2233-2234-2235-2236-2237-2238-2239-2240-2241-2242-2243-2244-2245-2246-2247-2248-2249-2250-2251-2252-2253-2254-2255-2256-2257-2258-2259-2260-2261-2262-2263-2264-2265-2266-2267-2268-2269-2270-2271-2272-2273-2274-2275-2276-2277-2278-2279-2280-2281-2282-2283-2284-2285-2286-2287-2288-2289-2290-2291-2292-2293-2294-2295-2296-2297-2298-2299-2300-2301-2302-2303-2304-2305-2306-2307-2308-2309-2310-2311-2312-2313-2314-2315-2316-2317-2318-2319-2320-2321-2322-2323-2324-2325-2326-2327-2328-2329-2330-2331-2332-2333-2334-2335-2336-2337-2338-2339-2340-2341-2342-2343-2344-2345-2346-2347-2348-2349-2350-2351-2352-2353-2354-2355-2356-2357-2358-2359-2360-2361-2362-2363-2364-2365-2366-2367-2368-2369-2370-2371-2372-2373-2374-2375-2376-2377-2378-2379-2380-2381-2382-2383-2384-2385-2386-2387-2388-2389-2390-2391-2392-2393-2394-2395-2396-2397-2398-2399-2400-2401-2402-2403-2404-2405-2406-2407-2408-2409-2410-2411-2412-2413-2414-2415-2416-2417-2418-2419-2420-2421-2422-2423-2424-2425-2426-2427-2428-2429-2430-2431-2432-2433-2434-2435-2436-2437-2438-2439-2440-2441-2442-2443-2444-2445-2446-2447-2448-2449-2450-2451-2452-2453-2454-2455-2456-2457-2458-2459-2460-2461-2462-2463-2464-2465-2466-2467-2468-2469-2470-2471-2472-2473-2474-2475-2476-2477-2478-2479-2480-2481-2482-2483-2484-2485-2486-2487-2488-2489-2490-2491-2492-2493-2494-2495-2496-2497-2498-2499-2500-2501-2502-2503-2504-2505-2506-2507-2508-2509-2510-2511-2512-2513-2514-2515-2516-2517-2518-2519-2520-2521-2522-2523-2524-2525-2526-2527-2528-2529-2530-2531-2532-2533-2534-2535-2536-2537-2538-2539-2540-2541-2542-2543-2544-2545-2546-2547-2548-2549-2550-2551-2552-2553-2554-2555-2556-2557-2558-2559-2560-2561-2562-2563-2564-2565-2566-2567-2568-2569-2570-2571-2572-2573-2574-2575-2576-2577-2578-2579-2580-2581-2582-2583-2584-2585-2586-2587-2588-2589-2590-2591-2592-2593-2594-2595-2596-2597-2598-2599-2600-2601-2602-2603-2604-2605-2606-2607-2608-2609-2610-2611-2612-2613-2614-2615-2616-2617-2618-2619-2620-2621-2622-2623-2624-2625-2626-2627-2628-2629-2630-2631-2632-2633-2634-2635-2636-2637-2638-2639-2640-2641-2642-2643-2644-2645-2646-2647-2648-2649-2650-2651-2652-2653-2654-2655-2656-2657-2658-2659-2660-2661-2662-2663-2664-2665-2666-2667-2668-2669-2670-2671-2672-2673-2674-2675-2676-2677-2678-2679-2680-2681-2682-2683-2684-2685-2686-2687-2688-2689-2690-2691-2692-2693-2694-2695-2696-2697-2698-2699-2700-2701-2702-2703-2704-2705-2706-2707-2708-2709-2710-2711-2712-2713-2714-2715

1001 235W-2 1 1 1

Hand of Joseph-Louis de ...

John of the - 11 11 11

11-10-1964

John- " " "

There is no doubt that the above is a very good example of a well-organized and well-written report. The report is clear, concise, and easy to read. It is a good example of how to write a report that is both informative and interesting.

WPA and WPA-2

no information to feed tests, not

Good no time to tell you

Journal of Health Politics, Policy and Law

The point of the low was around after the position went below "500"

in "Book One" was one on what he described as a

was noted to the cutting edge.

When the 2007-2008 season began, the 1000' was one foot "good".

Keep up the cut across the post office (100) without the wall showing

10051 VHS

A "fair" fool was one who could keep up the act forever.

Source: *Journal of the American Medical Association*, 1964, 191: 1000-1001.

"Istled" too blue not sure the one-let the sw and

across the test wire,

Make
at

M^cInn

do

do

do

do

Novo

do

do

Blue C

do

do

do

Bohler R

do

do

do

Vulcan

do

do

do

Albion

do

do

M^cInne

do

do

Novo

do

do

do

do

do

Blue C

do

do

do

Bohler R

do

do

Vulca

Albio

do

do

M^cInn

Blue C

Vulca

Bohler

Novo

Blue C

do

do

do

do

do

do

do

NAME TO JOURNAL: BUS. PERSON TO READ

And now, dear friends, I have the honor to

1001 5117-1 11 11 11

There are two types of...

John C. Smith - 8 8 8

3007-1001 NO 0000000000

... ..

angle between cutting edge and side of foot

WPA and WAC 2000

...and tests for the following

1001 80 72001 10 72001

[illegible]

The point of the test was to show that the test was not a test of the test.

in "Excess" and "too" was one on which no correctable change

was noted on the cutting edge.

before the above to get on how can I draw one and say "hoop"

Keep on the out some the sent also (108) without the work showing

• *Journal of Management Education* 32(10):1039-1050

"I think" feet was one which could keep up the old school.

1903 JUL 24 11 37 AM '03

"Failed" too blue ink on one side of the page

and across the test wire,

Make of Tool	Tool Number	Test Number	Cutting Speed Ft/min	Initial Dia Test Piece Inches	Final Dia Test Piece Inches	Actual Cut Inches	Actual Feed in./Rev	RPM	Wt. Cast Iron Pounds	Time min	K W	K W	Area of Test Piece Square Feet	Condition of Tool	Cause of Withdrawal	Area of Section of Tool Square Feet	Top Rate Degrees	Side Mach. Degrees	Front Clear. Degrees	Temper on Tool	Initial Circumference Inches	Final Circumference Inches	Cubic Inches Cast Iron	Test Piece Inches	Gears	Controller	Table VII	
McInnes	1	7	59.4	8.24	8.30	.06	.0625	28	58.724	434	8.0	.77	1.25	321	2.565	end	.00378	0	30	6-10	6	16.45	16.08	4.7	2	1	18	
do	2	8	59.8	8.24	8.30	.06	.0625	28	58.724	434	8.0	.77	1.25	321	2.565	end	.00378	0	30	6-10	6	16.45	16.08	4.7	2	1	18	
do	3	9	62.8	8.24	8.30	.06	.0625	28	58.724	434	8.0	.77	1.25	321	2.565	end	.00378	0	30	6-10	6	16.45	16.08	4.7	2	1	18	
do	4	10	64.0	8.24	8.30	.06	.0625	28	58.724	434	8.0	.77	1.25	321	2.565	end	.00378	0	30	6-10	6	16.45	16.08	4.7	2	1	18	
do	5	16.0	7.54	7.91	.05	.04	.04	81	37.153	918	2.25	2.5	7.71	1.860	good	failed	.00235	0	15	2.4	10.44	6.2	1	2	6	4		
Hove	1	6	116.0	7.46	7.57	.06	.06	58	61.181	966	3.47	2.3	2.08	1.863	good	end	.00378	0	15	2.4	10.44	6.2	1	2	6	4		
do	7	125.0	7.55	7.465	.041	.04	.04	63	37.118	672	3.17	2.3	1.57	1.40	2.00	good	end	.0026	0	15	2.4	10.44	6.2	1	2	6	4	
do	8	161.0	7.47	7.38	.04	.04	.04	88	31.134	745	2.33	2.3	2.25	1.835	2.25	failed	failed	.0023	0	15	2.4	10.44	6.2	1	2	6	4	
Blue Chip	1	9	106.5	7.24	7.24	.07	.04	55	45.134	745	3.37	1.3	1.33	1.55	2.00	good	end	.0044	0	13	2.31	2.75	4.7	1	2	6	4	
do	10	115.8	7.24	7.15	.045	.04	.04	61	38.610	715	3.12	2.5	1.5	1.04	1.933	good	end	.0028	0	13	2.31	2.75	4.7	1	2	6	4	
do	11	155.0	7.15	7.05	.050	.05	.05	93	3.3	139	3.36	2.28	47	2.05	1.09	2.0	good	end	.0031	0	13	2.31	2.75	4.7	1	2	6	4
do	12	159.0	7.05	6.965	.041	.04	.04	86	2.4	161	5.76	2.30	72	2.1	1.36	2.00	failed	end	.0025	0	13	2.31	2.75	4.7	1	2	6	4
Bühler Rapid	1	13	110.0	7.79	7.63	.075	.04	54	5.8	139	3.36	4.70	64	1.77	1.77	1.10	good	end	.0047	0	13	2.31	2.75	4.7	1	2	6	4
do	14	126.0	7.63	7.53	.05	.05	.05	65	4.7	137	7.17	3.50	32	1.67	1.65	2.00	good	end	.0031	0	13	2.31	2.75	4.7	1	2	6	4
do	15	176.0	7.53	7.43	.05	.05	.05	86	4.5	159	9.52	2.50	47	2.33	1.85	2.00	poor	end	.0031	0	13	2.31	2.75	4.7	1	2	6	4
do	16	157.3	7.43	7.324	.053	.05	.05	81	4.0	141	9.53	2.49	46	2.25	1.89	2.10	failed	failed	.0033	0	13	2.31	2.75	4.7	1	2	6	4
Volcan	1	17	106.6	7.324	7.19	.067	.06	54	5.1	128	7.71	3.58	60	1.75	1.50	1.10	good	end	.0042	0	13	2.31	2.75	4.7	1	2	6	4
do	18	120.6	7.19	7.074	.058	.06	.06	64	4.5	125	7.03	3.58	40	1.6	1.29	1.25	good	end	.0036	0	13	2.31	2.75	4.7	1	2	6	4
do	19	141.0	6.98	6.87	.055	.05	.05	77	3.9	131	7.93	2.56	45	2.1	1.71	1.30	good	end	.0034	0	13	2.31	2.75	4.7	1	2	6	4
do	20	153.0	6	5.85	.06	.06	.06	85	4.7	142	7.32	3.51	40	1.75	1.36	1.10	good	end	.0037	0	13	2.31	2.75	4.7	1	2	6	4
Albion	1	21	99.0	6.77	6.65	.06	.06	56	4.7	142	7.32	3.51	40	1.75	1.36	1.10	good	end	.0037	0	13	2.31	2.75	4.7	1	2	6	4
do	22	111.5	6.65	6.52	.065	.06	.06	64	4.3	123	7.40	3.20	35	1.675	1.56	1.10	good	end	.004	0	13	2.31	2.75	4.7	1	2	6	4
do	23	145.5	6.52	6.38	.065	.06	.06	85	4.0	141	9.53	2.49	46	2.25	1.89	2.10	failed	failed	.0033	0	13	2.31	2.75	4.7	1	2	6	4
McInnes	1	24	161.0	6.38	6.164	.107	.10	52	7.6	163	9.87	4.20	325	2.35	1.53	1.60	good	end	.0067	0	16	2.04	19.37	6.3	1	3	3	15
do	25	117.0	6.87	6.87	.105	.10	.10	63	6.0	121	12.65	3.31	35	2.85	1.67	1.45	good	end	.0065	0	16	2.04	19.37	6.3	1	3	3	15
do	26	126.0	6.87	6.64	.115	.11	.11	70	8.1	151	14.2	3.9	3.80	1.55	1.62	limit	end	.0072	0	21	5.9	20.87	9.3	1	3	3	15	
Hove	1	27	92.2	6.64	6.38	.13	.13	53	8.4	141	13.26	3.48	2.25	1.55	1.62	limit	end	.0072	0	15	2.08	20.04	8.5	1	3	3	15	
do	28	102.0	6.16	5.92	.12	.12	.12	63	7.0	160	12.60	3.21	3.2	1.59	1.73	good	end	.0075	0	19	36	18.62	7.7	1	3	3	15	
do	29	110.0	5.92	5.69	.115	.11	.11	71	6.8	133	13.2	2.56	2.6	1.57	1.62	good	end	.0075	0	19	36	18.62	7.7	1	3	3	15	
do	30	120.0	5.69	5.46	.115	.11	.11	80	6.1	126	14.6	2.35	375	2.85	1.61	1.60	good	end	.0072	0	17	90	17.17	9	1	3	3	15
do	31	114.0	5.46	5.24	.11	.11	.11	80	5.7	129	13.7	2.19	46	2.75	1.57	1.40	good	end	.0069	0	17	90	17.17	9	1	3	3	15
do	32	137.0	5.24	5.01	.115	.11	.11	93	2.8	110	16.0	2.0	4.3	3.0	1.66	1.63	failed	failed	.0072	0	17	90	17.17	9	1	3	3	15
Blue Chip	1	33	92.5	6.37	6.15	.11	.11	59	6.9	129	13.7	2.19	50	2.15	1.61	1.63	good	end	.0069	0	13	2.03	19.31	8.4	1	3	3	15
do	34	111.0	6.15	5.89	.13	.13	.13	69	6.6	141	14.9	2.44	375	2.7	1.58	1.52	good	end	.0081	0	13	19	18.56	8.3	1	3	3	15
do	35	121.0	5.89	5.63	.13	.13	.13	78	6.3	142	14.9	2.44	375	2.7	1.58	1.52	good	end	.0081	0	13	19	18.56	8.3	1	3	3	15
do	36	139.0	5.63	5.42	.105	.10	.10	94	6.7	130	18.60	2.0	48	3.6	1.15	1.50	limit	end	.0065	0	17	78	17.05	11.9	1	3	3	15
Bühler Rapid	1	37	100.0	5.42	5.20	.11	.11	70	5.7	110	16.0	2.0	48	3.6	1.15	1.50	good	end	.0069	0	20	17.05	16.34	6.1	1	3	3	15
do	38	105.0	5.06	4.79	.13	.13	.13	80	10.9	136	15.9	4.18	425	3.0	1.57	1.370	good	end	.0081	0	17	78	17.05	11.9	1	3	3	15
do	39	148.0	4.79	4.54	.13	.13	.13	118	1.37	1.57	1.57	1.57	1.57	1.57	1.57	1.57	failed	failed	.0043	0	18	14.25	13.32	9.1	1	3	3	15
Volcan	1	40	121.0	4.54	4.34	.10	.10	102	6.1	148	11.0	3.18	56	2.6	1.61	1.30	good	end	.0069	0	13	16.5	16.34	6.1	1	3	3	15
Albion	1	41	103.0	4.34	4.12	.11	.11	90	5.4	116	15.6	2.30	74	2.2	1.50	1.30	good	end	.0069	0	13	16.5	16.34	6.1	1	3	3	15
do	42	111.0	4.12	3.94	.135	.13	.13	96	3.1	153	15.30	1.13	42	3.3	1.58	1.32	limit	end	.0081	0	13	16.5	16.34	6.1	1	3	3	15
do	43	68	4.3	4.17	.18	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
McInnes	1	44	68	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
Blue Chip	1	45	68	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
Volcan	2	46	65.5	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
Bühler Rapid	1	47	65.5	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
Hove	1	48	65.5	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
Blue Chip	1	49	65.5	4.3	4.15	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
do	50	65.5	4.3	4.15	.18	.18	.18	28	6.8	229	17.4	2.1	715	3.378	2.08	1.499	failed	failed	.0074	0	29.19	2.722	11.1	2	2	1	2	1
do	51	96.5	8.38	7.67	.355	.0312	.0312	72	2.2	119	7.1	1.20																



Make of Tool	Tool Number
Blue Chip	1 5
"	1 5
Daye	1 6
"	1 6
"	1 6
"	1 6
"	1 6
"	1 6
"	1 6
"	1 6
Libon	10 6
Blue Chip	1 6
"	1 7
Libon	10 7



Table IV
continued[illegible]

DISCUSSION of the TEST of

HIGH SPEED STEEL on CAST IRON.

(a) Hardening the Tools. See table IX.

A mistake was made in the directions given us for hardening "Albion" high speed steel. In order to investigate the difference in the quality of the tool when heated to different temperatures and cooled in an air blast or oil, we conducted a series of experiments with a muffle furnace and pyrometer, heating twelve small pieces of the metal to temperatures varying from 1375°F. to (2250°F.) , or a good white heat. All the pieces heated below 1800°F. were soft. The quality of the tool ~~increased~~^{increased} gradually from 1800°F. to 2000° , and at 2200°F. a good, hard, tough tool was obtained by cooling in an air blast. A muffle furnace is not desirable for hardening lathe tools because it will not give the necessary high temperature. Also, even if a high temperature is available, it is not best to use one for lathe tools unless some method is provided for heating only the nose of the tool to a white heat. If the entire tool is hardened it is very apt at heavy loads to break off under the set screw. As few heats as possible should be used on any one tool. The high heats necessary for tempering lathe tools is liable to melt the edges of the body of the tool when using a muffle furnace. When placing the tools in the air blast for hardening it was found to be advantageous to only ~~heat~~^{have} about one inch of the nose of the tool to be exposed to the blast, thus allowing the neck of the tool to cool down slowly and add to the toughness of the tool.

(a) Hardening the Tool. See Table IX.

A mistake was made in the directions given as for hardening "Aldison" high speed steel. In order to investigate the difference in the results of the heat treatment of different materials and cooled in an air blast or oil, we conducted a series of experiments with a muffle furnace and pyrometer, heating twelve small pieces of the metal to temperatures varying from 1475°F . to 2320°F . or a good white heat. All the pieces heated below 1800°F . were soft. The first six of the heat treated pieces from 1800°F to 2000°F and 2100°F a good, hard, tough tool was obtained by cooling in an air blast. A muffle furnace is not desirable for hardening these tools because it will not give the necessary high temperature. Also, even if a high temperature is available, it is not best to use one for these tools unless some method is provided for heating only the nose of the tool to a white heat. If the entire tool is hardened it is very soft and heavy tools to break off under the set screw. A few heats are necessary. The high heats necessary for tempering these tools is liable to melt the edges of the body of the tool when using a muffle furnace. When placing the tools in the air blast for hardening it was found to be advantageous to only heat about the back of the nose of the tool to be exposed to the blast thus allowing the neck of the tool to cool down slowly and due to the cooling of the tool.

(b) Grinding the Tools.

It is an essential in grinding a high speed tool that care be taken not to force the tool against the wheel or allow one point to remain in contact with the same line on the wheel. Surface cracks will be produced if the tool becomes too hot while using water. These cracks tend to reduce the quality of the tool and in some cases cause it to break. Two of the "Vulcan" tools broke due to cracks made while grinding.

(c) Results.

For a certain constant feed and cut a series of runs were made on each of the six different grades of steel, the cutting speed in ft./min. being increased for each succeeding run until the tool failed. The accompanying blue print shows the performance of each tool.

Summary of Results from Blue Print.

Tool	Cut&Feed inches	Sustained speed ft./min.	#C. I. removed per min.	Area of cut sq. in.	Area of mach'd sq. ft.	Condi- tion of tool.
McInnes	.05x.0625	134	1.39	.0031	0.7	good
Novo	.042x.0625	125	1.12	.0026	0.64	"
Blue Chip	.05x.0625	155	1.39	.0031	0.809	"
Bohler rapid.	.05x.0625	170	1.59	.0031	0.883	poor
Vulcan	.055x.0625	141	1.31	.0034	.731	good
Albion	.065x.0625	111.5	1.23	.006	.566	"
McInnes	.115x.0625	126	2.57	.0072	.655	limit
Novo	.11x.0625	114	2.29	.0069	.597	good
Blue Chip	.105x.0625	139	3.10	.0065	.725	limit
Bohler Rapid.	.13x.0625	105	2.56	.0081	.551	good
Albion	.135x.0625	111	2.55	.0084	.559	limit

It is an essential in grinding a high speed tool that care be taken not to force the tool against the wheel or allow one point to remain in contact with the same line on the wheel. Surface cracks will be produced if the tool becomes too hot while using water. These cracks tend to reduce the quality of the tool and in some cases cause it to break. Two of the "Vulcan" tools broke due to cracks while grinding.

(c) Results.

For a certain constant feed and a series of runs were made on each of the six different grades of steel, the cutting speed in ft./min. being increased for each succeeding run until the tool failed. The accompanying line graph shows the performance of each tool during its life from nine runs.

Tool	Grinding speed ft./min.	Grinding speed ft./min.	Grinding speed ft./min.	Grinding speed ft./min.	Grinding speed ft./min.	Grinding speed ft./min.
Machine	154	154	154	154	154	154
Wave	154	154	154	154	154	154
Blue Chip	154	154	154	154	154	154
Bohler rapid	154	154	154	154	154	154
Vulcan	154	154	154	154	154	154
Wave	154	154	154	154	154	154
Machine	154	154	154	154	154	154
Wave	154	154	154	154	154	154
Blue Chip	154	154	154	154	154	154
Bohler rapid	154	154	154	154	154	154
Vulcan	154	154	154	154	154	154

Tool	Cut&Feed inches	Sustained speed ft./min.	#C. I. removed per min.	Area of Cut sq. in.	Area Mach'd sq. ft.	Condition of tool
Scale cut	1/8-1/4x1/8	68	2.89	.0117	.208	excellent
Blue Chip	.355x.0312	136	4.6	.0111	.355	"
" "	.175x.0312	145	2.14	.0054	.374	good
Novo	.18x.0312	190	2.41	.0056	.491	excellent
Albion	.18x.0312	169	2.0	.0056	.438	failed
Blue Chip	.195x.0312	180	3.37	.0061	.465	good
" "	.18x.0312	207	4.15	.0056	.535	"

All tools failed on the next highest speed^{above that} given in the above

table.

Condition of tool	Time of use, min.	Speed, ft./min.	Amount of material removed, cu. in.	Condition of tool	Time of use, min.	Speed, ft./min.	Amount of material removed, cu. in.
Excellent	0.12	1.50	2.30	Scale cut 1/8-1/4x1/8	0.12	1.50	2.30
"	0.12	1.50	4.6	Blue chip .500x.0512	0.12	1.50	4.6
Good	0.12	1.50	2.14	" .125x.0512	0.12	1.50	2.14
Excellent	0.12	1.50	2.41	" .125x.0512	0.12	1.50	2.41
Failed	0.12	1.50	2.0	" .125x.0512	0.12	1.50	2.0
Good	0.12	1.50	2.27	Blue chip .125x.0512	0.12	1.50	2.27
"	0.12	1.50	4.15	" .125x.0512	0.12	1.50	4.15

All tools failed on the next highest speed given in the above

The tools used in this test were
worked according to the directions furnished
by the makers as stated on the following pages.

The tools used in this test were
worked according to the directions furnished
by the makers as stated on the following pages.

COMPOSITION of HIGH SPEED TOOL STEEL.

The following may be given as the composition of a well known High Speed Steel:

Muck (Swedish).....	45.0 Lbs.
Special Tool Scrap.....	40.0 Lbs.
Washed Metal.....	10.0 Lbs.
Ferro-chromium.....	5.0 Lbs.
Clay.....	4.0 Lbs.

When iron is melted the crucible is taken from the furnace and slag removed. Before replacing the following are added:

Ferro-silicon.....	1.5 Lbs.
Ferro-manganese.....	0.5 Lbs.
Metallic Tungsten.....	20.0 Lbs.
Flux.....	1.5 Lbs.

The object of the clay is to act as a decarbonizer and it proves very efficient. It removes the alloys to a large extent except chromium (probably by forming silicates) consequently these are not added until the clay is removed. The crucible is then replaced for thirty minutes.

1947 1948 1949 1950 1951 1952 1953 1954 1955 1956 1957 1958 1959 1960 1961 1962 1963 1964 1965 1966 1967 1968 1969 1970 1971 1972 1973 1974 1975 1976 1977 1978 1979 1980 1981 1982 1983 1984 1985 1986 1987 1988 1989 1990 1991 1992 1993 1994 1995 1996 1997 1998 1999 2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 2577 2578 2579 2580 2581 2582 2583 2584 2585 2586 2587 2588 2589 2590 2591 2592 2593 2594 2595 2596 2597 2598 2599 2600 2601 2602 2603 2604 2605 2606 2607 2608 2609 2610 2611 2612 2613 2614 2615 2616 2617 2618 2619 2620 2621 2622 2623 2624 2625 2626 2627 2628 2629 2630 2631 2632 2633 2634 2635 2636 2637 2638 2639 2640 2641 2642 2643 2644 2645 2646 2647 2648 2649 2650 2651 2652 2653 2654 2655 2656 2657 2658 2659 2660 2661 2662 2663 2664 2665 2666 2667 2668 2669 2670 2671 2672 2673 2674 2675 2676 2677 2678 2679 2680 2681 2682 2683 2684 2685 2686 2687 2688 2689 2690 2691 2692 2693 2694 2695 2696 2697 2698 2699 2700 2701 2702 2703 2704 2705 2706 2707 2708 2709 2710 2711 2712 2713 2714 2715 2716 2717 2718 2719 2720 2721 2722 2723 2724 2725 2726 2727 2728 2729 2730 2731 2732 2733 2734 2735 2736 2737 2738 2739 2740 2741 2742 2743 2744 2745 2746 2747 2748 2749 2750 2751 2752 2753 2754 2755 2756 2757 2758 2759 2760 2761 2762 2763 2764 2765

The following may be given as the composition of a well

1. *Costs* have a 0.25 weight.

with (b) and (c) are

[illegible]

doi:10.1371/journal.pone.0142407.g002

ref 0.2 unbound-crit

2017 04 20 10:00:00

When iron is added the sample is taken to the furnace

and also removed, before releasing the following are added:

.....non-fission.....

ad C.C. PERSONS - CITE.

95% CI: 0.03, 0.07. *P* = 0.0001. *OR* = 1.0001. *P* = 0.0001.

ad: c.

The object of the day is to get a decision and if the respondent is not a decision-maker, to get a decision-maker.

THE UNIVERSITY OF CHICAGO PRESS

and chronic (probably by forming alliances) consequently these are

not added until the clay is removed. The straight is then released.

for entry within

List of the Various Steels Used in the Tests.

- (1) "Vulcan" High Speed Tool Steel. Made by the Vulcan Crucible Steel Company of Aliquippa, Pa.
- (2) "Bohler Rapid" Self Hardening Steel. Made by Bohler Bros. & Co., Styrian Steel Works, Vienna, Austria. Houghton & Richards, Agents, of Boston, Mass. and Chicago, Ill.
- (3) "Air Novo" High Speed Steel. Herman Boker & Co.
- (4) "Blue Chip" High Speed Steel. Made by the Firth-Sterling Steel Company at Pittsburgh, Pa.
- (5) "Albion" High Speed Self Hardening Steel. Made by Hobson Houghton & Co., Ltd., Don Steel Wks., Sheffield, England. Chas. G. Stevens, Chicago Agents.
- (6) McInnes "Extra" High Speed, Air-Hardening Steel. Made by the McInnes Steel Co., Ltd., Corry, Pa.

List of the Various Steels Used in the Tests.

- (1) "Vulcan" High Speed Tool Steel. Made by the Vulcan Steel Company of Pittsburgh, Pa.
- (2) "Doherty Rapid" Self-Hardening Steel. Made by Doherty Bros. & Co., Egyptian Steel Works, Vienna, Austria. Houghton & Sons, Agents, of Boston, Mass. and Chicago, Ill.
- (3) "Air Novo" High Speed Steel. Norman Hoker & Co. Steel Company at Pittsburgh, Pa.
- (4) "Blue Chip" High Speed Steel. Made by the first-mentioned Houghton & Sons, Ltd., von Steel Works, Sheffield, England. Houghton & Sons, Agents.
- (5) "Mannes" High Speed, Air-Hardening Steel. Made by the Mannes Steel Co., Ltd., Germany.

[illegible]

Instructions for Forging and Hardening Grades of HIGH SPEED TOOL STEELS.

These instructions were furnished by the makers of the steels.
For lathe, planer, and similar tools.

(1) Instructions for working "Air Novo" steel.

The bar should not be broken cold: it should be cut off hot.

FORGING.- The heating should be done slowly in a well burned through, hollow, coal fire or in a charcoal fire and care taken that the heat has thoroughly "soaked" through the end which is to be forged and the forging should be done at a high lemon color heat. The heat color should be like the glowing fibre of an incandescent lamp and the steel should be so hot that it forges on an anvil with a dull sound and without a metallic ring, giving readily under the forging hammer. This lemon color heat is absolutely necessary in forging. Time may be saved by grinding the tool on a dry emery wheel while the forged tool is still red hot from the forge. After forging, permit the tool to grow cold by itself on the floor.

HARDENING.- Take the forged tool which, as stated above, should be permitted to grow cold gradually, and bring the forged end or nose into a well burned through, coal or charcoal fire (not a gas furnace because a gas furnace will not make the steel hot enough) slowly to a white heat. This extreme white heat should confine itself to about $1/2$ to $3/4$ of an inch from the nose of the tool and should be so hot that the steel begins to fuse and blister. This high heat is absolutely necessary. Do not allow the air blast in the forge to play on the point of the tool.

These instructions were furnished by the makers of the steels.

For lathe, planer, and similar tools.

(1) Instructions for working "Air Hove" steel.

The bar should not be broken cold: it should be cut off hot.

FORGING. - The heating should be done slowly in a well burned

through, hollow, coal fire or in a charcoal fire and care taken that

the heat has thoroughly "soaked" through the end which is to be forged

and the forging should be done at a high lemon color heat. The heat

color should be like the glowing fire of an incandescent lamp and

the steel should be so hot that it forges on an anvil with a dull

round and without a metallic ring, giving readily under the forging

hammer. This lemon color heat is absolutely necessary in forging.

Time may be saved by grinding the tool on a dry emery wheel while the

forged tool is still red hot from the forge. After forging permit

the tool to grow cold by itself on the floor.

HARDENING. - Take the forged tool which, as stated above,

should be permitted to grow cold gradually, and bring the forged end

or nose into a well burned through, coal or charcoal fire (not a gas

furnace because a gas furnace will not make the steel hot enough)

slowly to a white heat. This extreme white heat should continue long

to about $\frac{1}{8}$ to $\frac{3}{4}$ of an inch from the nose of the tool and should

be so hot that the steel begins to flame and blister. This high heat

is absolutely necessary. Do not allow the air blast in the forge to

play on the point of the tool.

At this white fusing heat, quickly draw the tool from the fire and put the white hot part in contact with the strongest and coldest air blast which is available, letting the tool get cool so that it may be picked up with the bare hand. Compressed air will give the best results, however, good results are secured with as low as two pounds of air. Under all conditions avoid bringing the tool into contact with water while hot.

Equally good results are obtained by hardening the white hot nose of the tool in free running oil (that is, so that cool oil at about 80°F. or less comes continually in contact with the hot tool) Kerosene, fish oil, or lard oil will give the best results. The tool should be permitted to grow comfortably cold in the oil, all the time keeping cold oil in contact with the tool and then the cooling off process should be continued in a cold blast. When the tool is thrust into the oil it should be given a motion in a direction parallel to the sides of the stock of the tool. The white hot nose of the tool should touch the oil first. After the tool comes out of the oil the nose must show signs of having been fused a trifle and must have a greyish white appearance.

GRINDING.- Grind on a wet emery wheel but with a plentiful supply of water and not too forcibly as surface cracks might be created. These cracks might cause the tool to break off.

A dry emery wheel could be used taking care that the steel does not become discolored. See that grinding wheel is not glazed.

(2) Instructions for working "Blue Chip" high speed steel.

(a) For lathe, planer, and similar roughing tools.

is this white flaking heat, probably from the
fire and not the white hot part in contact with the strongest and cold
hot air blast which is available, testing the cool part so that
it may be checked up with the bare hand. Compressed air will give the
best results. However, good results are secured with as low as two
pounds of air. Under all conditions avoid bringing the cool into
contact with water while hot.

Usually good results are obtained by rendering the white hot
nose of the tool in free running oil (that is no hot oil at
about 300°, or less comes continually in contact with the hot tool).
Kerosene, fish oil, or lard oil will give the best results. The tool
should be permitted to grow comfortably cold in the oil, all the time
keeping cold oil in contact with the tool and then the cooling oil
process should be continued in a cold blast. When the tool is thrust
into the oil it should be given a motion in a direction parallel to
the sides of the stock of the tool. The white hot nose of the tool
should touch the oil first. After the tool comes out of the oil the
nose must show signs of having been treated a trifle and must have a
grayish white appearance.

WARNING - Grind on a wet emery wheel but with a plentiful
supply of water and not too forcibly as surface cracks might be created.
These cracks might cause the tool to break off.

A dry emery wheel could be used taking care that the steel
does not become discolored. See that grinding wheel is not glazed.
(2) Instructions for working "blue chip" high speed steel.
(a) For lathe, planer, and similar turning tools.

FIRE.- For this class of tools a good fire is one made of hard foundry coke, broken into small pieces, in an ordinary blacksmith forge with a few bricks laid over the top to form a hollow fire. The fire must be well burned through, and solid, so that the blast does not touch the tool. The bricks should ^{be} thoroughly heated before the tools are hardened. Hard anthracite coal may be used very successfully in place of hard coke and will give a higher heat.

FORGING.- Heat the nose of the tool slowly and uniformly to a good forging heat. Do not hammer the tool after it has cooled below a bright red heat. Avoid as much as possible heating the body of the tool, so that the natural toughness in the neck of the tool is retained. Time can be saved by grinding the tool while red hot from the forge.

HARDENING.- Heat the point of the tool to an extreme white heat until the flux runs. This heat should be the highest possible short of the melting point. Care should be taken to confine the heat to the end of the tool so that the tool will retain its natural toughness in the neck where it is held in the tool post.

Draw the tool quickly from the fire and cool in a good air blast, or in oil such as fish or cotton-seed. 5

Grind the tool on a dry emery wheel.

For finishing tools harden according to the directions for hardening milling cutters. (See next page).

This is a good fire in one side of
 and forming coke, broken into small pieces, in an ordinary blast
 force with a few bricks laid over the top to form a hollow fire. The
 fire must be well burned through, and solid, so that the blast does
 not touch the cool. The bricks should thoroughly heated before the
 coals are kindled. And another cool may be used very advantage-
 fully in place of part coke and will give a higher heat.
 FURNACE. - Heat the nose of the cool slowly and uniformly to
 a good working heat. Do not hammer the cool after it has cooled and
 low a bright red heat. Avoid as much as possible heating the cool
 of the cool, so that the natural toughness in the neck of the cool is
 retained. This can be saved by grinding the cool while red hot from
 the forge.
 BURNING. - Heat the point of the cool to an extreme white
 heat until the flux runs. This heat should be the highest possible
 short of the melting point. Care should be taken to confine the heat
 to the end of the cool so that the cool will retain the natural tough-
 ness in the neck where it is held in the cool point.
 Draw the cool quickly from the fire and cool in a good air
 blast, or in oil such as fish or cotton-seed.
 Grind the cool on a dry emery wheel.
 For finishing tools handle according to the directions for
 resending all the rollers (see next page).

(b) For Milling Cutters, Drills, Taps, Reamers, Formed Cutters, and similar tools.

FIRE.- Gas furnaces designed for high heats are now made and do very satisfactory work in hardening this class of tools. There are furnaces on the market made especially for this purpose. Where a furnace is not convenient these tools can be hardened in a forge fire as described for hardening lathe and similar tools but care must be taken to keep the tool away from contact with the fuel.

HARDENING.- Tools should be heated to a white heat just below the blistering point. The heat should be the highest possible in view of the importance of preserving the cutting edges. The higher the heat the better the tool. In cooling, quench in oil immediately when taken from the fire as described for lathe tools.

For this class of tools and for lathe finishing tools draw the temper to a dark straw color of about 500°F.

(3) Instructions for working "Vulcan" high speed steel. Heat the tools to an absolute white or welding heat and then cool in oil (not kerosene).

With tools of intricate shape or having fine or sharp edges, heat as near a white heat as possible and cool as above.

This steel cannot be hurt by burning.

(b) for Milling Cutters, Drills, Taps, Reamers, Formed Cutters, and
similar tools.

NOTE. - The furnaces designed for high heats are now made and
is very satisfactory work in hardening this class of tools. There are
furnaces on the market made especially for this purpose. Where a fur-
nace is not convenient these tools can be hardened in a large tank
described for retreating tools and similar tools but care must be taken
to keep the tool away from contact with the fuel.

REMARKS. - Tools should be heated to a white heat that be-
low the blistering point. The heat should be the highest possible
in view of the importance of preserving the cutting edges. The high-
er the heat the better the tool. In cooling, quench in oil immedi-
ately when taken from the fire as described for lathe tools.
For this class of tools and for lathe finishing tools draw
the temper to a dark straw color of about 500°F.

(3) Instructions for working "Vulcan" high speed steel.
Heat the tools to an absolute white or welding heat and then
cool in oil (not kerosene).
With tools of intricate shape or having fine or sharp edges,
heat as near a white heat as possible and cool as above.
This steel cannot be heat treated by burning.

(4) Instructions for working McInnes "EXTRA" High Speed, Air-Hardening Steel.

FORGING. - Heat the steel (away from the blast) slowly, thoroughly, and evenly at the ordinary tool steel forging heat taking care to heat the steel uniformly to the center: then shape the tool. Avoid hammering the steel when it has cooled below a dull red.

HARDENING. - After the tool is forged to the desired shape reheat the cutting end until it sweats or just before it runs: then cool off in an air blast or dip in fish oil.

(5) Instructions for working "ALBION" High Speed Self-Hardening Steel.

FORGING. - Heat gradually but thoroughly to a cherry red, in the same manner as tempering Tool Steel.

HARDENING. - Reheat to a white heat and cool in oil.

(6) Instructions for working "BOHLER RAPID" Styrian High Speed Steel.

FORGING. - Heat to a bright yellow color. Do not allow the heat to run as low as a cherry red while forging. After forging allow the tool to cool slowly before hardening.

HARDENING. - For lathe, planer, and boring tools heat to a white heat but not to a scaling or melting point. Cool in air or in a cold blast. For milling cutters, taps, reamers, and twist drills heat as above and cool in fish oil. The temper of the latter class of tools should be drawn in tempering oil.

14) Instructions for working in sand "dry" high speed. 14-
hardening steel.

WORKING - Heat the steel (away from the glass) slowly,
thoroughly, and evenly at the ordinary tool forging heat being
care to heat the steel uniformly to the center: when above the tool.
Avoid hammering the steel when it has cooled below a dull red.
HARDENING - After the steel is formed to the desired shape
repeat the cooling and until it is above or just below it turn: then
cool off in an air blast or dip in fish oil.

15) Instructions for working "dry" high speed self-hardening
tool steel.

WORKING - Heat gradually but thoroughly to a cherry red, in
the same manner as tempering tool steel.
HARDENING - Repeat to a white heat and cool in oil.
16) Instructions for working "dry" high speed system when cooled

steel.
WORKING - Heat to a bright yellow color. Do not allow the
steel to run as low as a cherry red while forging. After forging
allow the steel to cool slowly before hardening.
HARDENING - For faster, cleaner, and better tools heat to a
white heat but not to a melting or melting point. Cool in air or
in a cold blast. For milling cutters, taps, reamers, and twist drills
heat as above and cool in fish oil. The center of the latter class
of tools should be drawn in tempering oil.

BIBLIOGRAPHY

LITERATURE RELATING TO HIGH SPEED TOOL STEELS.

"Notes on High Speed Tool Steels":by H.H.Suplee, in Engineering, (London), July 31, 1903.

The article discusses the results of some tests made at the Union Pacific R.R. Shops, Omaha, Nebraska.

"Rapid Cutting Tool Steels":in Engineering (London) Oct. 30, 1903.

The article discusses and presents the report on some experiments made at the Manchester Municipal School of Technology. The article is written by Prof. J. T. Nicholson. Prof. Nicholson conducted the tests personally.

Same article as above reported in the American Machinist, for Nov. 19 and 26, 1903.

The Engineering Magazine for May, 1906, page 231. An article on "High Speed Steel in the Factory" written by O.M. Becker. The article states and discusses the four conditions affecting the economy of a tool. First cost, accuracy of work, cost of maintenance in an efficient state, and endurance. The article states the different purposes and kinds of tools for which High Speed Tool Steel may be used.

"Tests of High Speed Tool Steels on Cast Iron". A very fine article by L.P. Breckenridge and H.B. Dirks in "American Machinist" Vol. 29 Number 10. The article gives a description, with illustrations, of some experiments made in the shops at the University of Illinois.

University of Illinois Bulletin. "Tests of High Speed Tool Steels on Cast Iron". Nov. 15, 1905. Vol. 3. Number 4. Issued by the Engineering Experiment Station. Complete details of the tests in book form.

THE JOURNAL OF THE INSTITUTION OF MECHANICAL ENGINEERS

"Notes on High Speed Tool Steels" by H.A. Swaine, in Engineering

(London), July 25, 1903.

The article discusses the results of some tests made at the

United States Steel Corporation, West Chester, Ohio.

"High Speed Tool Steels" in Engineering (London), Vol. 2, 1903.

The article discusses and presents the report on some experi-

ments made at the Manchester Municipal School of Technology. The

article is written by Prof. J.E. Nicholson, F.R.S., who conducted

the tests personally.

Some articles as above referred to in the American Machinist, for Nov.

1903 and 20, 1904.

The Engineering Magazine for May, 1905, page 241. An article on

"High Speed Steel in the Factory" written by G.M. Becker. The article

states and discusses the four conditions affecting the economy of a

factory, (1) the economy of materials, (2) the economy of machine

time, and (3) the economy of labor. The article states the different purposes and

uses of tool steels for which high speed steel may be used.

"Notes of High Speed Tool Steels on Heat Treat", a very fine arti-

cle by L. Buchenberger and H.A. Swaine in "American Machinist", Vol. 20,

Number 10. The article gives a description, with 12 illustrations, of some

experiments made in the shop at the University of Illinois.

University of Illinois Bulletin, "Notes of High Speed Tool Steels"

for 1905, Nov. 25, 1905, Vol. 2, Number 4. Edited by the engineer-

ing community. Complete details of the tests in book form.

"High Speed Steel in the Factory"-Engineering Magazine Sept. 1905, page 931. Gives a general review of the field. This is the first of a series of articles written by O.M. Becker and Walter Brown.

"Metal Working Tools"-Engineering Magazine 1903, page 932. The article is very good dealing with the various effects of cuts, feeds, and speeds.

"Report of the Franklin Institute"-Engineering Magazine, 1903 Vol. 25, page 121. The article deals with the Taylor-White Tool Steel and discusses various processes of treating tool steels to obtain the maximum efficiency at high cutting speeds.

"Tests at the Manchester Municipal School of Technology"-Eng. Mag. 1904, Vol. 27, page 913. Article by D.A. Wilt Jr.

Proc. A.S.M.E. Vol. 24, page 351.

Iron Age, Apr. 7, 1904 & Dec. 1, 1904.

Machinery, Apr. 1905 & Apr. 1906.

Proc. A.S.M.E. Vol. 25, page 105 & Vol. page 49

Iron and Steel Mag., Mch. 1906.

The Iron Trade Review, Apr. 2, 1904.

"Testing Cast Iron"-The Foundry, May 1906.

The Iron Trade Review, July 14, Aug. 4 & 25, 1904.

The Engineering Magazine, Sept. 1904.

The Iron and Steel Magazine, Jan. 1905, page 19.

Proc. of the Western Railway Club. Article by J.A. Carney, Dec. 1903.

"High Speed Steel in the Railway"-Engineering Magazine, 1904, page 281. Gives a general review of the field. This is the first of a series of articles written by O. M. Becker and Walter Brown.

"Metal Working Tools"-Engineering Magazine, 1904, page 282. The article is very good dealing with the various effects of cuts, feeds, and speeds.

"Report of the Franklin Institute"-Engineering Magazine, 1904, Vol. 28, page 281. The article deals with the Taylor-White Tool tests and discusses various processes of treating tool steels to obtain the maximum efficiency at high cutting speeds.

"Tests at the Manchester Municipal School of Technology"-Eng. Mag., 1904, Vol. 27, page 281. Article by G. A. Wilf Jr.

Proc. A. S. M. E. Vol. 24, page 281.

From the Apr. 7, 1904 & Dec. 1, 1904.

Engineering, Jan. 1903 & Jan. 1904.

Proc. A. S. M. E. Vol. 23, page 282 & Vol. 24, page 281.

Iron and Steel Mag., March 1904.

The Iron Trade Review, Jan. 2, 1904.

"Steel Cast Iron"-The Iron Age, May 1904.

The Iron Trade Review, July 12, Aug. 4 & 25, 1904.

The Engineering Magazine, Sept. 1904.

The Iron and Steel Magazine, Jan. 1905, page 281.

Proc. of the Western Railway Club. Article by G. A. Cannon, Dec. 1904.

"Rapid Cutting Steel"-Technics, Jan. 1904. Article by Prof. J. T. Nicolson. Gives a formula for finding the allowable cutting speed in feet per minute for various materials.

"Heat Treatment of Steel"-Proceedings of the Institute of Mechanical Engineers, Jan. 1904. A discussion of the hardening, annealing, and chemical properties of steel.

"The Introduction of High Speed Steels in Engineering Work Shops". Engineering (London), March 4, 1904. Vol. 77.

"High Speed Tool Steel": Its Manufacture and Use, by J. M. Jledhill-Technics, Part 1, June 1904; Part 2, July 1904. Some of the materials and processes used in the manufacture of high speed steel.

"Experiments with a Lathe Tool Dynamometer"-A. S. M. E., Vol. 25, 1904. Article written by Prof. J. T. Nicolson. The apparatus measures all forces acting on a lathe tool while cutting. A discussion of the influence of cutting angles on the power required to cut.

"A Twist Drill Dynamometer"-A. S. M. E. Vol. 26, 1904. The apparatus measures both the torque and the twist of the drill while cutting with high speed drills.

"The Chemical Analysis of High Speed Steels and Alloys"-Technics Oct. 1904. Article by F. Ibbotson.

"Feeds and Speeds for Lathe Work"-American Machinist, May 25, 1905. Tests made at the Cincinnati Milling Machine Co. Shops.

"The Practical Handling of High Speed Steel"-Iron and Steel Mag. Jan. 1905, Vol. 9, page 251.

"Report of some High Speed Steel Tests"-Iron and Steel Magazine, Vol. 10, page 237.

"Steel Cutting Speeds" Technical Jan. 1904. Title by Vol. 1, 11.

Nickelson. Gives a formula for finding the average cutting speed in feet per minute for various materials.

"Heat Treatment of Steel" - Proceedings of the Institute of Mechanical Engineers, Jan. 1904. A discussion of the hardening, annealing and chemical properties of steel.

"The Introduction of High Speed Steels in Engineering Work" - Engineering (London), March 4, 1904. Vol. 7.

"High Speed Tool Steels: The Manufacture and Use, by J. M. Nichols" - Technical, Part I, June 1904; Part II, July 1904. Some of the properties and processes used in the manufacture of high speed steel.

"Experiments with a High Tool Dynamometer" - J. M. Nichols, Vol. 12, 1904. Article written by Vol. 12, 1904. The dynamometer is forced to act on a lathe tool while cutting. A discussion of the influence of cutting angles on the power required to cut.

"Twist Drill Dynamometer" - J. M. Nichols, Vol. 12, 1904. The dynamometer measures both the torque and the twist of the drill while cutting with high speed drills.

"The Chemical Analysis of High Speed Steels and Alloys" - Technical, Vol. 1904. Article by J. M. Nichols.

"Tests and Results for the Work" - American Machinist, May 21, 1904. Tests made at the Cincinnati Milling Machine Co. shops.

"The Practical Handling of High Speed Steels" - Iron and Steel Mag., Jan. 1905. Vol. 2, page 101.

"Report of some High Speed Steel Tests" - Iron and Steel Magazine, Vol. 1, 1905.

"Experiments with a New Tool Steel"-Stahl and Eisen, Jan. 1, 1901.
The above article was written by F. Heissig. It gives the report of some tests made by Bohler Bros. and Co. on their "Bohler Rapid" steel.

"The Taylor-White process of treating tool steel and its influence on the mechanic arts"-Journal of the Franklin Institute, Sept. '01.

"High Speed Tool Steel"-Stahl and Eisen, Jan. 15, 1903. The article discusses the chemical properties of high speed and self-hardening steels.

"Speeds, Feeds, and Angles of Metal-Cutting Tools"-American Machinist, Mch. 5, 1903. The article discusses the relation of the cutting angles to the angles to which the tools are ground.

"The Requirements of Machine Tool Operation with special reference to Motor Drive"-American Machinist, March 12, 1903 (contains Part I) Mch. 19, 1903 (contains Part II). The article was written by Mr. C. Day and contains a very good discussion of electrically driven machine tools.

"Cutting Speeds and Feeds with New Tool Steels"-Engineering Mag. Vol. 26, Jan. 1904. Article written by Mr. Oberlin Smith containing a record of results secured with the steel.

"Metal Cutting with the New Tool Steels"-Engineering Mag. Vol. 25, Apr. 1903. Article by Mr. Oberlin Smith which contains a discussion of the changes in machine tools brought about by the introduction of high speed steel.

"Rapid Tool Steels"-Engineering (London) Vol. 76, Aug. 21, 1903. Discussion of chemical properties and attainable speeds with H. S. steel.

Fred Norwood Wilson
Charles Edward Hayes

"Experiments with a New Tool Steel" - (1911) and (1912) Jan. 1911
The above article was written by J. H. Pomeroy, and gives the results of
some tests made by Robert H. Pomeroy, and also on their "Experiments with a New Tool Steel"
"The Taylor-White process of treating tool steel and the results of the
on the mechanical properties of the Franklin Institute, Phila. Pa.
"High Speed Tool Steel" - (1911) and (1912) Jan. 1911, 1912
Article discusses the chemical properties of high speed and tool-
hardening steels.
"Speeds, Feeds, and Angles of Metal-Cutting Tools" - (1911) Jan. 1911
Article, Vol. 1, No. 1. The article discusses the relation of the cutting
angles to the angles to which the tools are ground.
"The requirements of machine tool operation with special refer-
ence to motor drive" - (1911) Western Mechanist, March 1911, Vol. 1, No. 1
The article was written by Wm. H. McMillan, and contains a very good discussion of the
requirements of machine tool operation with special reference to motor drive.
"Cutting Speeds and Feeds with New Tool Steels" - (1911) Engineering Mag.
Vol. 1, No. 1, Jan. 1911. Article written by Wm. H. Pomeroy, and contains
a record of results secured with the above.
"Metal Cutting with the New Tool Steel" - (1911) Engineering Mag. Vol. 1, No. 1
Article by Wm. H. Pomeroy, which contains a discussion of the changes in machine tool
operation caused by the introduction of high speed steel.
"Speeds, Feeds, and Angles of Metal-Cutting Tools" - (1911) Engineering Mag. Vol. 1, No. 1
Article written by Wm. H. Pomeroy, and contains a discussion of the changes in machine tool
operation caused by the introduction of high speed steel.

TABLE of CONTENTS.	PAGE.
PRELIMINARY DISCUSSION.....	1
DESCRIPTION of LATHE (Illustrated).....	3
TABLE of FEED INDEX.....	7
TABLE of SPEEDS and GEARS (Illustrated).....	8
EFFICIENCY TEST of the LATHE (Illustrated).....	10
DESCRIPTION of ELECTRICAL CONNECTIONS (Diagram)	12
TABLES of RESULTS of EFFICIENCY TESTS	13
CURVES " " " " "	19
DISCUSSION of RESULTS of EFF. TEST of LATHE.....	31
PREPARATION of TEST PIECE for LATHE (Diagram).....	33
DESCRIPTION of GRINDING MACHINE	35
" " MACHINE for HARDNESS TEST (Illustrated)	36
" " TEST of HIGH SPEED STEEL TOOLS (Illustrated)..	39
TABLE GIVING RELATIVE DIAMETERS, SPEEDS, and REVOLUTIONS	41
TABLE of RESULTS of the HIGH SPEED STEEL TESTS	44
DISCUSSION of " " " " " " "	46
COMPOSITION of HIGH SPEED STEEL	50
List of the STEELS used in the TESTS	51
TABLE GIVING METHOD of HARDENING TOOLS	52
INSTRUCTIONS for FORGING and HARDENING TOOLS.....	53
BIBLIOGRAPHY	58

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS

CONTENTS







